



Bison Oil Well Cementing Inc.
1738 Wynkoop St.
Suite 102
Denver, CO 80202
303-296-3010

| |
|---|
| Bill To |
| Noble Energy Inc. Attn: Accounting 1625 Broadway Ste 2000 Denver, CO 80202 |

| | |
|-----------|-----------|
| Invoice # | 3/23/2012 |
| 11419 | |

Invoice

| | | | |
|-----------|-------------------|--------|--------------|
| Location | Well Name & No. | Terms | Job Type |
| Weld, CO. | Chenoweth C20-25D | Net 30 | Surface Pump |

| Item | Description | Qty | U/M | Rate | Amount |
|------|-------------|-----|-----|------|--------|
|------|-------------|-----|-----|------|--------|

| | | | | | |
|-----------------------|--------------------------|-----|------|----------|-----------|
| Pump surface | PUMP Charge-surface pipe | 1 | | 1,400.00 | 1,400.00 |
| Discount 15% | | | | -15.00% | -210.00 |
| MILEAGE | Mileage charge | 360 | | 1.50 | 540.00 |
| Discount 15% | | | | -15.00% | -81.00 |
| Data Acquisition ... | Data Acquisition Charge | 1 | | 225.00 | 225.00 |
| Discount 15% | | | | -15.00% | -33.75 |
| BFN III Winter ... | BFN III Blend | 318 | Sack | 18.25 | 5,803.50T |
| Discount 15% | | | | -15.00% | -870.53 |
| KCL Mud Flush | (BHS 117) | 5 | qt | 7.50 | 37.50T |
| Discount 15% | | | | -15.00% | -5.63 |
| Dye - 4880 | Dye (Hot Pink 4880) | 10 | oz | 15.00 | 150.00T |
| Discount 15% | | | | -15.00% | -22.50 |
| Subtotal of Materials | | | | | 5,092.34 |

Please Remit Payment To:

Bison Oil Well Cementing, Inc.
P.O. Box 29671
Thornton, CO 80229

| | |
|------------------|------------|
| Subtotal | \$6,932.59 |
| Sales Tax (2.9%) | \$147.68 |
| Total | \$7,080.27 |
| Balance Due | \$7,080.27 |

BISON OIL WELL CEMENTING, INC.



1738 Wynkoop St., Ste. 102
 Denver, Colorado 80202
 Phone: 303-296-3010
 Fax: 303-298-8143
 E-mail: bisonoil@qwestoffice.net

SERVICE INVOICE

№ 11419

| | | | | | | | |
|-------------------|--|---------------|--|-------------------------|--|------------|--|
| WELL NO. AND FARM | | COUNTY | | STATE | | DATE | |
| Chenoweth C20-850 | | Weld | | CO | | 3/23/12 | |
| CHARGE TO | | WELL LOCATION | | TWP. | | RANGE | |
| Juchu | | Sec. 80 | | 4N | | 64W | |
| DELIVERED TO | | SHIPPED VIA | | TYPE AND PURPOSE OF JOB | | WELL TYPE | |
| 4251 | | 3/01 | | 3207 | | 3 Shot | |
| LOCATION | | LOCATION | | LOCATION | | LOCATION | |
| 1 Shot | | 425 | | 425 | | 3 Shot | |
| CONTRACTOR | | CONTRACTOR | | CONTRACTOR | | CONTRACTOR | |
| Ensign 126 | | Ensign 126 | | Ensign 126 | | Ensign 126 | |

| PRICE REFERENCE | DESCRIPTION | QTY. | MEAS. | UNIT PRICE | AMOUNT |
|-----------------|--|------|-------|------------|---------|
| | Pump charge | 1 | each | 1400.00 | 1400.00 |
| | BFA 3% BCC A-1.25 lbs/sk BFLY-1 | 318 | sk | 18.35 | 5803.50 |
| | BFLY-1 | 5 | cts | 750.00 | 37.50 |
| | Bye | 10 | 02 | 15.00 | 150.00 |
| | Mileage 8.150/mi 60 mile per hour trip | 3 | each | 180.00 | 540.00 |
| | Peds To | 1 | each | 925.00 | 925.00 |
| | Loaded Miles | | | | |
| | Ton Miles | | | | |

| | |
|---|-------------------|
| BRNO | Ensign 126 |
| WELL NAME & NO. | Chenoweth C20-850 |
| PROJECT NO. | 12657 |
| TAXP. COMP. W/O. PAY. | Consolidated |
| ACTG. CODE | 11 0017 |
| DOLLAR TOTAL DEMAND | 8886 |
| DATE | 3-2-12 |
| 1ST LEVEL APPROVAL | |
| 2ND LEVEL APPROVAL | |
| MAIL TO: NOBLE ENERGY INC. 1525 BROADWAY SUITE 2200 DENVER, CO 80202 | |
| TOTAL WEIGHT | |

TAX REFERENCES

SUB TOTAL
 TAX
 TOTAL

"TAXES WILL BE ADDED AT CORPORATE OFFICE"

SUBJECT TO CORRECTION

Bison Oil Well Cementing, Inc. Representative

Customer or His Agent

Customers hereby acknowledge and specifically agree to the terms and conditions on this work order, including, without limitation, the provisions on the reverse side hereof which include the release and indemnity.

If this account is not paid within 30 days of invoice date a FINANCE CHARGE will be made. Computed at a single monthly rate of 1 1/2% which is equal to an ANNUAL PERCENTAGE RATE OF 18%.

Bison Oil Well Cementing, Inc
1738 Wynkoop St., Ste. 102
Denver, CO 80202
303-296-3010
www.bisonoilwell.com



Cementing Customer Satisfaction Survey

| | | | |
|-------------------------|--------------|----------------------|-----------|
| Invoice Number | 11119 | Invoice Amount | 3/23/12 |
| Well Permit Number | 665 | Well Name | Chaparral |
| Well Type | 665 | Well Location | S14 |
| Well Number | 20-250 | County | Weld |
| Lease | | SEC/WP/RNG | 20 4N 64W |
| Job Type | Surface pipe | State | CO |
| Company Name | Weld | Supervisor Name | WIK |
| Customer Representative | Barndy | Employee Name | |
| Customer Phone Number | | Total Exposure Hours | |

Did we encounter any problems on this job? Yes ☐ No ☒

To Be Completed By Customer

- Rating/Description**
- 5 - Superior Performance (Established new quality / performance standards)
 - 4 - Exceeded Expectations (Provided more than what was required / expected)
 - 3 - Met Expectations (Did what was expected)
 - 2 - Below Expectations (Job problems / failures occurred [* Recovery made])
 - 1 - Poor Performance (Job problems / failures occurred [* Some recovery made])
- * Recovery: resolved issue(s) on jobsite in a timely and professional manner

RATING / CATEGORY

- Personnel -
- Equipment -
- Job Design -
- Product / Material -
- Health & Safety -
- Environmental -
- Timeliness -
- Condition / Appearance -
- Communication -
- Improvement -

CUSTOMER SATISFACTION RATING

- Did our personnel perform to your satisfaction?
- Did our equipment perform to your satisfaction?
- Did we perform the job to the agreed upon design?
- Did our products and materials perform as you expected?
- Did we perform in a safe and careful manner (Pre / post migs, PPE, TSMR, etc..) ?
- Did we perform in an environmentally sound manner (Spills, leaks, cleanup, etc..) ?
- Was job performed as scheduled (On time to site, accessible to customer, completed when expected)?
- Did the equipment condition and appearance meet your expectation?
- How well did our personnel communicate during mobilization, rig up, and job execution?
- What can we do to improve our service?

Please Circle:

- Yes / No - Did an accident or injury occur?
- Yes / No - Did an injury requiring medical treatment occur?
- Yes / No - Did a first-aid injury occur?
- Yes / No - Did a vehicle accident occur?
- Yes / No - Was a post-job safety meeting held?
- Yes / No - Was a pre-job safety meeting held?
- Yes / No - Was a job safety analysis completed?
- Yes / No - Were emergency services discussed?
- Yes / No - Did environmental incident occur?
- Yes / No - Did any near misses occur?

THE INFORMATION HEREIN IS CORRECT -

Customer Representative's Signature

Any additional Customer Comments or HSE concerns should be described on the back of this form

Date

3/23/12



1738 Wynkoop St., Ste. 11
Denver, Colorado 80202
Phone: 303-296-3010
Fax: 303-298-8143
E-mail: bisonoil1@qwestoffice.net

B.O.C. Tailgate Safety Meeting Report

INVOICE

11/19

Meeting Facilitator

Tucker, L. [Signature]

Work to be Undertaken

Surface Pipe

Time

10:18 AM

Facility Name and Location

Chunath 20-25D

Nearest Emergency Medical Service Number (Other than 911)

1149

MINIMUM STANDARDS REQUIREMENT VERIFICATION (must be verified for all members of a work party)

Hard Hat Safety Glasses w/sideshield Safety Toed Footwear Personal Methane Monitor Verify Safety Training

Flame Resistant Clothing New on Job Review Onsite Orientation Other (specify)

HAZARD IDENTIFICATION AND SAFETY BRIEFING DISCUSSION (Check and Discuss all Relevant Hazards)

- ☒ Hazardous Substance
- ☒ Hazardous Atmosphere
- ☒ Walking/Working Surfaces
- ☒ Noise Levels
- ☒ Sharp Edges
- ☒ Insects/Snakes/etc.
- ☒ MSDS's Reviewed
- ☒ Walk Around Site Assessment

ADDITIONAL PPE REQUIREMENT (based on the job specific hazards, check all that apply)

- ☒ Eyes/Face
- ☒ Tinted Lenses
- ☒ Goggles
- ☒ Face Shield
- ☒ Hearing Protection
- ☒ Hands
- ☒ Chemical Resistant Gloves
- ☒ Heat Resistant Gloves
- ☒ Cotton or Leather Gloves
- ☒ Dielectric Gloves
- ☒ Feet
- ☒ Rubber Boots
- ☒ Over Boots
- ☒ Dielectric Boots
- ☒ Other
- ☒ Air Purifying Respirator
- ☒ Supplied Air Respirator
- ☒ Personal H2S Monitor (if in sour area)
- ☒ Chemical Resistant Clothing
- ☒ Personal Fall Arrest Systems

EMERGENCY PREPARATIONS

Muster Areas Communication Methods Means of Egress Emergency Equipment

Additional Topics Covered:

Attendees (Signature)/Company

Attendees (Signature)/Company

Other Considerations and Field Notes:

Stone Pile Design 11/29/18
134748
11/15/88
11/19