

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
08/09/2012

Document Number:
663300393

Overall Inspection:
Unsatisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>218340</u>	<u>312128</u>		<u>SCHURE, KYM</u>

Operator Information:

OGCC Operator Number: 7800 Name of Operator: BEREN CORPORATION
 Address: 2020 N BRAMBLEWOOD STREET
 City: WICHITA State: KS Zip: 67206

Contact Information:

Contact Name	Phone	Email	Comment
Richmond, Emma	(316) 337-8370	ecrichmond@berexco.com	

Compliance Summary:

QtrQtr: SWSW Sec: 30 Twp: 6N Range: 54W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/25/2010	200233105	PR	PR	S			N
05/22/2003	200039430	PR	PR	S		P	N
04/01/2003	200037295	PR	PR	U		F	Y
01/04/1996	500152470	PR	PR			P	N
12/14/1995	500152469	PR	PR			P	N

Inspector Comment:

Incorrect/Invalid/Non-existent signage and placarding. Stained soils. Leaking equipment. Berm requires repairs and maintenance.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
218340	WELL	PR	04/12/1982	OW	075-05019	SEGELKE 1	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Unsatisfactory	Placards are required on all tanks/vessels including quantities.	Install sign to comply with rule 210.b.	09/24/2012
BATTERY	Unsatisfactory	Emergency contact no. 303-295-2323 received by answering machine. Sign at battery is required to list all associated wells.	Install sign to comply with rule 210.b.	09/24/2012
WELLHEAD	Unsatisfactory	NO sign at wellhead	Install sign to comply with rule 210.b.	09/24/2012

Emergency Contact Number: (S/U/V) Unsatisfactory Corrective Date: 09/24/2012

Comment: Emergency contact no. is required to be answered by a live attendant 24-7-2012

Corrective Action: Install signage to comply with 210 rules.

Spills:				
Type	Area	Volume	Corrective action	CA Date
Crude Oil	Tank	<= 5 bbls	Remove or remediate stained soil on battery floor and berm walls.	09/24/2012
Crude Oil	WELLHEAD	<= 5 bbls	Repair leak at stuffing box. Remove or remediate stained soil at wellhead.	09/24/2012
Lube Oil	Pump Jack	<= 5 bbls	Remove or remediate stained soil in pump shack. Install containment for 55gal. barrel of lubricant in pump shack.	09/24/2012

Multiple Spills and Releases?

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Vertical Heated Separator	1	Satisfactory			
Bird Protectors	1	Satisfactory			
Pump Jack	1	Unsatisfactory		Install containment for 55gal. barrel of lubricant in pump shack or berm pump-jack area. Remove or remediate stained soil at	09/24/2012
Ancillary equipment	1	Satisfactory	Propane tank at separator		
Deadman # & Marked	4	Unsatisfactory		Mark deadman for year-round visibility	09/24/2012

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST	40.000000,103.000000
S/U/V:	Unsatisfactory		Comment: Tank quantities on placard	
Corrective Action:	Placarding to comply with 210 rules.			Corrective Date:
Paint				
Condition				
Other (Content)	_____			
Other (Capacity)	_____			
Other (Type)	_____			
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Corrective Action	Repair and maintain berm at battery. Height of berm walls inadequate			Corrective Date 09/24/2012
Comment				
Venting:				
Yes/No	Comment			
Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 312128

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 218340 Type: WELL API Number: 075-05019 Status: PR Insp. Status: PR

Producing Well

Comment: Spills less than 5bbl. require removal or remediation. Signage is incorrect/invalid/non-existent. NO containment for chemical additives/lubricants at wellhead/pump jack.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____