

FORM
INSPRev
05/11State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/20/2012

Document Number:

663400778

Overall Inspection:

Unsatisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name
	239967	317785		EDELEN, RANDY

Operator Information:

OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER

State: CO

Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Pavelka, Linda	(303) 228-4064	LPavelka@nobleenergyinc.com	

Compliance Summary:

QtrQtr: SWNE Sec: 32 Twp: 3N Range: 65W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/30/1998	500161696	BH	PR			P	N

Inspector Comment:

Producing well

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
239967	WELL	PR	08/05/2011	OG	123-07755	JACOB SCHLEGEL 1	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory			
WELLHEAD	Satisfactory			

Inspector Name: EDELEN, RANDY

TANK LABELS/PLACARDS	Unsatisfactory	Information incomplete	Install sign to comply with rule 210.b.	09/30/2012
----------------------	----------------	------------------------	---	------------

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: Verified

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
Crude Oil	WELLHEAD	<= 5 bbls	Remove or remediate stained soil	09/30/2012
Crude Oil	Separator	<= 5 bbls	Remove or remediate stained soil	09/30/2012
Crude Oil	Truck Loadout	<= 5 bbls	Remove or remediate stained soil	09/30/2012

☒ Multiple Spills and Releases?

Fencing:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory			
WELLHEAD	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Heated Separator	1	Unsatisfactory	Leaking	Repair and maintain equipment	09/30/2012
Plunger Lift	1	Unsatisfactory	Leaking	Repair and maintain equipment	09/30/2012
Bird Protectors	2	Satisfactory			
Gas Meter Run	1	Satisfactory			
Flow Line	1	Unsatisfactory	Leaking	Repair and maintain equipment	09/30/2012
Emission Control Device	1	Satisfactory			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST	40.184430,-104.684490

S/U/V: Satisfactory Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) Not labeled

Other (Capacity) Not labeled

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate

Corrective Action: Repair and build a berm of adequate capacity Corrective Date: 09/30/2012

Comment: Path worn through berm, location is not level berm is too low

Inspector Name: EDELEN, RANDY

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLS		,
S/U/V:	Satisfactory	Comment:	Openings not screened	
Corrective Action:				Corrective Date:
Paint				
Condition				
Other (Content)	Not labeled			
Other (Capacity)	80 bbl			
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Corrective Action				Corrective Date
Comment	See steel tank for inspection of common berm			
Venting:				
Yes/No	Comment			
YES	Master valve leaking			
Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ignitor/Combustor	Satisfactory			

Predrill

Location ID: 317785

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 239967 Type: WELL API Number: 123-07755 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Environmental**Spills/Releases:**

Inspector Name: EDELEN, RANDY

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a.	Debris removed? _____	CM _____	
	CA _____		CA Date _____
	Waste Material Onsite? _____	CM _____	
	CA _____		CA Date _____
	Unused or unneeded equipment onsite? _____	CM _____	
	CA _____		CA Date _____
	Pit, cellars, rat holes and other bores closed? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Guy line anchors removed? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Guy line anchors marked? _____	CM _____	
	CA _____		CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: EDELEN, RANDY

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass

Recontoured Pass

80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: Location is in a scrap yard

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs

BMP
Maintenance

Lease Road Erosion
BMPs

Lease BMP
Maintenance

Chemical BMPs

Chemical BMP
Maintenance

Comment

S/U/V: Satisfactory

Corrective Date: _____

Comment: _____

CA: _____