

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

08/21/2012

Document Number:

661602076

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

|                     |               |               |               |                      |
|---------------------|---------------|---------------|---------------|----------------------|
| Location Identifier | Facility ID   | Loc ID        | Tracking Type | Inspector Name:      |
|                     | <u>421423</u> | <u>421455</u> |               | <u>MONTOYA, JOHN</u> |

**Operator Information:**

OGCC Operator Number: 16660 Name of Operator: CHESAPEAKE OPERATING INC

Address: P O BOX 18496

City: OKLAHOMA CITY State: OK Zip: 73154-

**Contact Information:**

| Contact Name    | Phone          | Email                | Comment |
|-----------------|----------------|----------------------|---------|
| Anderson, Sandi | O 307-234-9045 | sandy.andrew@chk.com |         |

**Compliance Summary:**

|              |           |            |             |                              |            |                |                 |
|--------------|-----------|------------|-------------|------------------------------|------------|----------------|-----------------|
| QtrQtr: NWNE |           | Sec: 15    | Twp: 6N     |                              | Range: 62W |                |                 |
| Insp. Date   | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I   | Pas/Fail (P/F) | Violation (Y/N) |
| 03/16/2012   | 661600941 | PR         | PR          | U                            |            |                | N               |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   |                                     |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------------------------------|
| 421423      | WELL | PR     | 12/14/2011  | OW         | 123-32910 | Hoff 6-62 15-1H | <input checked="" type="checkbox"/> |

**Equipment:****Location Inventory**

|                              |                         |                      |                         |
|------------------------------|-------------------------|----------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: <u>2</u> | Wells: <u>1</u>      | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: <u>2</u>   | Separators: <u>3</u> | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____     | LACT Unit: _____     | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____     | Oil Pipeline: _____  | Water Pipeline: _____   |
| Gas Compressors: <u>1</u>    | VOC Combustor: <u>1</u> | Oil Tanks: <u>8</u>  | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____  | Flare: <u>1</u>      | Fuel Tanks: _____       |

**Location**

| <b>Signs/Marker:</b> |                             |  |   |            |
|----------------------|-----------------------------|--|---|------------|
| Type                 | Satisfactory/Unsatisfactory | Comment  | Corrective Action                       | CA Date    |
| WELLHEAD             | Unsatisfactory              | JUST TAKE SIGN FROM ENTERING LOCATION AND PUT IT ON WELLHEAD AND WE SHOULD BE OK | Install sign to comply with rule 210.b. | 09/22/2012 |

Emergency Contact Number: (S/U/V) \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Inspector Name: MONTROYA, JOHN

Comment:

Corrective Action:

**Spills:**

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

**Venting:**

| Yes/No | Comment |
|--------|---------|
|--------|---------|

**Flaring:**

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
|------|-----------------------------|---------|-------------------|---------|

**Predrill**

Location ID: 421455

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

| Group | User     | Comment   | Date       |
|-------|----------|---|------------|
| OGLA  | koepsear | Under rule 902.(f) Unlined pits shall not be constructed on fill material. The provided drawing show that the proposed pit is partially constructed therefore the following COA will apply :<br><br>All pits constructed in fill material shall be lined. | 01/20/2011 |

**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

|              |         |            |         |
|--------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
|              |         |            |         |

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:****Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 421423 Type: WELL API Number: 123-32910 Status: PR Insp. Status: PR

### Environmental

#### Spills/Releases:

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

#### Water Well:

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

#### Field Parameters:

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

### Reclamation - Storm Water - Pit

#### Interim Reclamation:

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

Inspector Name: MONTOYA, JOHN

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In  
Production areas have been stabilized? In Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Fail

1003 f. Weeds Noxious weeds? I

Comment: \_\_\_\_\_

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_