

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

03/16/2012

Document Number:

663000055

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>422085</u>	<u>428671</u>		<u>KING, KEVIN</u>

Operator Information:OGCC Operator Number: 5 Name of Operator: COLORADO OIL & GAS CONSERVATION COMMISSIONAddress: 1120 LINCOLN ST SUITE 801City: DENVERState: COZip: 80203**Contact Information:****Compliance Summary:**QtrQtr: NWNE Sec: 28 Twp: 8S Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/23/2012	663100053			S			N
04/06/2012	663100052			S			N
04/05/2012	663100051			S			N
04/04/2012	663100050			S			N
03/23/2012	663200010	TA	TA	U			N
03/22/2012	663000051	TA	TA	S			N
03/21/2012	663000049	TA	TA	S			N
03/20/2012	663000047	TA	TA	S			N
03/17/2012	663000045	TA	TA	S			N
03/15/2012	663000041	TA	TA	S			N
03/14/2012	663000039	TA	TA	S			N
03/12/2012	663000037	TA	TA	S			N
03/09/2012	663000035	TA	TA	S			N
03/08/2012	663000033	TA	TA	S			N
03/07/2012	663000031	TA	TA	S			N
03/06/2012	663000029	TA	TA	S			N
03/05/2012	663000027	TA	TA	S			N
03/02/2012	663000025	TA	TA	S			N
03/01/2012	663000021	TA	TA	S			N
03/01/2012	663100043	TA	TA	S			N
02/29/2012	663000019	TA	TA	S			N
02/28/2012	663000017			S			N
02/27/2012	663000015			S			N
02/24/2012	663000013			S			N
02/23/2012	663000011			S			N

Inspector Name: KING, KEVIN

02/22/2012	663000009			S			N
02/21/2012	663000007			S			N
06/21/2011	663100018	TA	TA	S			N
04/07/2011	200306887	PM	TA	S			N
03/22/2011	200306884	PM	TA	S			N
12/01/2010	200301811	PM	TA	S			N
11/17/2010	200307581	PM	TA	S			N
11/16/2010	200301806	PM	TA	S			N
11/11/2010	200307574	PM	TA	S			N
11/08/2010	200307555	PM	TA	S			N
11/07/2010	200307549	PM	TA	S			N
11/06/2010	200307543	PM	TA	S			N
11/05/2010	200307517	PM	TA	S			N
11/04/2010	200307514	PM	TA	S			N
11/03/2010	200307508	PM	TA	S			N
11/02/2010	200302701	PM	TA	S			N
10/25/2010	200301766	PM	TA	S			N
10/22/2010	200301764	PM	TA	S			N
10/21/2010	200301762	PM	TA	S			N
10/20/2010	200301687	PM	TA	S			N
10/19/2010	200301685	PM	TA	S			N
10/19/2010	200307452	PM	TA	S			N
10/18/2010	200307464	PM	TA	S			N
10/15/2010	200307462	PM	TA	S			N
10/14/2010	200307458	PM	TA	S			N
10/13/2010	200301682	PM	TA	S			N
10/12/2010	200302682	PM	TA	S			N
10/12/2010	200301680	PM	TA	S			N
10/11/2010	200301676	PM	TA	S			N
10/08/2010	200301673	PM	TA	S			N
10/07/2010	200301670	PM	TA	S			N
10/06/2010	200307445	PM	TA	S			N
10/06/2010	200301667	PM	TA	S			N
10/05/2010	200301659	PM	TA	S			N
10/04/2010	200301657	PM	TA	S			N
10/01/2010	200302653	PM	TA	S			N
09/24/2010	200301634	PM	TA	S			N
	200307450	PM	TA	S			N

Inspector Comment:

Project manager (PAWR) on the DeBeque Plugging Project. Please see the attached daily report.

Inspector Name: KING, KEVIN

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name		
422085	WELL	TA	03/16/2011	OW	077-40011	DB Orphan Pasture 1	<input checked="" type="checkbox"/>	

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 428671

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 422085 Type: WELL API Number: 077-40011 Status: TA Insp. Status: TA

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: KING, KEVIN

Comment: <input style="width:700px" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
Field Parameters:			
<input style="width:300px" type="text"/>			
Sample Location: <input style="width:400px" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit

Interim Reclamation:			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: _____			
Comment: <input style="width:700px" type="text"/>			
1003a.	Debris removed? _____ CM _____		
	CA _____	CA Date _____	
	Waste Material Onsite? _____ CM _____		
	CA _____	CA Date _____	
	Unused or unneeded equipment onsite? _____ CM _____		
	CA _____	CA Date _____	
	Pit, cellars, rat holes and other bores closed? _____ CM _____		
	CA _____	CA Date _____	
	Guy line anchors removed? _____ CM _____		
	CA _____	CA Date _____	
	Guy line anchors marked? _____ CM _____		
	CA _____	CA Date _____	
1003b.	Area no longer in use? _____		Production areas stabilized ? _____
1003c.	Compacted areas have been cross ripped? _____		
1003d.	Drilling pit closed? _____		Subsidence over on drill pit? _____
	Cuttings management: _____		
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____		
	Production areas have been stabilized? _____		Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION			
<u>Cropland</u>			
	Top soil replaced _____	Recontoured _____	Perennial forage re-established _____

Inspector Name: KING, KEVIN

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
663000056	Daily Report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2974765