

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/16/2012

Document Number:

668200120

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>209769</u>	<u>382297</u>		<u>LEONARD, MIKE</u>

Operator Information:

OGCC Operator Number:	<u>70100</u>	Name of Operator:	<u>PHILLIPS PETROLEUM CO</u>
Address:	<u>P O BOX 1967</u>		
City:	<u>HOUSTON</u>	State:	<u>TX</u>
		Zip:	<u>77251-</u>

Contact Information:

Contact Name	Phone	Email	Comment
Shaffer, Jessie	(719) 488-2525	JessieS@woodmoorWater.com	
SCHOEPFLIN, SHARON		sharon.schoepflin@state.co.us	
Robinson, Kristy	(505) 326-9739	Kristy.a.robinson@conocophillips.com	Regulatory Supervisor
HELGELAND, GARY		gary.helgeland@state.co.us	

Compliance Summary:QtrQtr: NWNW Sec: 27 Twp: 16S Range: 65W**Inspector Comment:**

CURRENT LANDOWNER IS WOODMOOR WATER AND SANITATION DISTRICT. JESSIE SHAFFER IS DISTRICT MANAGER OFFICE PHONE # IS 719-488-2525 X 14. CONTACT COGCC PRIOR TO CORRECTIVE ACTION DATE TO.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
209769	WELL	PA	01/01/1999		041-05014	NILES 1	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: <u>(S/U/V)</u> _____	Corrective Date: _____
Comment: _____	
Corrective Action: _____	

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Inspector Name: LEONARD, MIKE

☐ Multiple Spills and Releases?

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 382297

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 209769 Type: WELL API Number: 041-05014 Status: PA Insp. Status: PA

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: LEONARD, MIKE

Comment: <input style="width: 700px;" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
Field Parameters:			
<input style="width: 300px;" type="text"/>			
Sample Location: <input style="width: 400px;" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: LEONARD, MIKE

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: GRASSLAND

Well plugged Pass

Pit mouse/rat holes, cellars backfilled Fail

Debris removed Fail

No disturbance /Location never built _____

Access Roads Regraded Pass

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present Pass

Subsidence _____

Comment: FOUND PIT IN PLACE, HOWEVER IS GRASSED OVER. LARGE CEMENT BLOCKS ARE STILL IN PLACE. MET WITH RANCH MANAGER TRAVIS SMITH TO DISCUSS CEMENT. HE SAID HE WOULD CONTACT OWNERS AS TO HAVING REMOVED OR NOT.

Corrective Action: REMOVE BLOCKS AND EVALUATE FOR POSSIBLE WELLBORE. SAMPLE PIT AREA TO ENSURE NO SUBSURFACE CONTAMINATION. RECLAIM ALL DISTURBED AREAS. SEE FURTHER INSTRUCTIONS ON COMMENT PAGE 1

Date **09/30/2012**

Overall Final Reclamation

Fail

Multi-Well Location



Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

COGCC Comments

Comment	User	Date
URGENT LANDOWNER IS WOODMOOR WATER AND SANITATION DISTRICT. JESSIE SHAFFER IS DISTRICT MANAGER OFFICE PHONE # IS 719-488-2525 X 14. CONTACT COGCC PRIOR TO CORRECTIVE ACTION DATE TO.	leonardm	08/26/2012

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668200121	Cement pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2977032
668200122	Cement Block	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2977033