

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/23/2012

Document Number:

668200133

Overall Inspection:

Violation**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>206042</u>	<u>321101</u>		<u>LEONARD, MIKE</u>

Operator Information:

OGCC Operator Number: 10114 Name of Operator: S & S OIL & GAS OPERATING

Address: 107 N 4TH STE 209

City: PONCA CITY State: OK Zip: 74601

Contact Information:

Contact Name	Phone	Email	Comment
BURN, DIANA		diana.burn@state.co.us	
QUINT, CRAIG		craig.quint@state.co.us	
WEEMS, MARK		mark.weems@state.co.us	

Compliance Summary:

QtrQtr: <u>SWNE</u>	Sec: <u>11</u>	Twp: <u>35S</u>	Range: <u>46W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/27/2011	200316360	RT	SI	U			Y
06/22/2010	200257336	RT	SI	U			Y
08/03/2009	200216210	RT	SI	U			Y
02/17/2009	200207496	ES	SI	U			Y
07/16/2008	200193297	MI	SI	S			N
07/11/2007	200114839	RT	SI	S		P	N
08/01/2006	200094749	RT	AC	S		P	N
02/10/2005	200066923	RT	SI	S		P	N
08/10/2004	200058057	RT	SI	S		P	N
07/29/2003	200042220	MI	SI	S		P	N
08/08/2002	200029692	RT	AC	S		P	N
08/23/2001	200019481	RT	AC	S		P	N
02/23/2001	200015394	PR	AC	S	I	P	N
03/03/2000	200005080	RT	AC	S	I	P	N
05/04/1999	500136412	PR	AC			P	N
06/11/1998	500136411	PR	AC			P	N
02/13/1997	500136410	PR	AC			P	N

Inspector Comment:

INSPECTED LOCATION FOR ORPHAN WELL PLUGGING EVALUATON. NO CHANGE IN EQUIPMENT SINCE LAST INSPECTION

Related Facilities:

Inspector Name: LEONARD, MIKE

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
206042	WELL	SI	01/05/2001	DSPW	009-06458	TSRU 701W	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 321101

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 206042 Type: WELL API Number: 009-06458 Status: SI Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____S/V: ViolationCA Date: 12/31/2012

CA: Well must be either: 1) Put on production or 2) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production or 3) Be properly plugged and abandoned. 4) A sundry requesting continued temporarily abandoned status should be submitted to Bob Koehler at the COGCC within thirty (30) days of receipt of this report - the sundry should detail the plan for the future operation of the well and the way the well is closed to the atmosphere. Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Comment: NEED TO PLUG WELL AND RECLAIM LOCATION**Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Inspector Name: LEONARD, MIKE

Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____