

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/23/2012

Document Number:

669300086

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>NEIDEL, KRIS</u>
	<u>264342</u>	<u>324728</u>		

Operator Information:OGCC Operator Number: 8960 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLCAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
wolfe, stephen	303-882-0224	swolfe@bonanzacrk.com	operation engineer

Compliance Summary:

QtrQtr: <u>SENE</u>	Sec: <u>3</u>	Twp: <u>9N</u>	Range: <u>79W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/18/2011	200319025	RT	AC	S			N
08/25/2010	200268574	RT	AC	S	I		N
08/05/2009	200216092	RT	AC	S			N
12/10/2008	200200661	RT	AC	S			N
08/10/2004	200058634	PR	PR	S		P	N
08/11/2003	200042811	PR	PR	S	F	F	N
08/12/2002	200030047	DG	ND	S		P	N

Inspector Comment:

On location for MIT of injection well. Well passed MIT. no equipment other than wellhead.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
264342	WELL	IJ	06/30/2008	DSPW	057-06425	MCCALLUM 177	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Inspector Name: NEIDEL, KRIS

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TRASH	Unsatisfactory	old rail road ties, electric conduit left over from well being a pumper.	Remove equipment not essential for production or injection.	05/01/2013

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:		
Yes/No	Comment	
NO		

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 324728

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 264342 Type: WELL API Number: 057-06425 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: PRREB

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 12/05/2007

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Method of Injection: PUMP FEED

Test Type: 5 Year Tbg psi: 450 Csg psi: 760 BH psi: _____

Insp. Status: Pass

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Fail CM old rail road ties, electric conduit left over from well being a pumper.CA Remove equipment not essential for production or injection. CA Date 05/01/2013Waste Material Onsite? Fail CM old rail road ties, electric conduit left over from well being a pumper.CA Remove equipment not essential for production or injection. CA Date 05/01/2013Unused or unneeded equipment onsite? Fail CM old rail road ties, electric conduit left over from well being aCA Remove equipment not essential for production or injection. CA Date 05/01/2013Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? Pass
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	Pass			

Inspector Name: NEIDEL, KRIS

Gravel	Pass				
Compaction	Pass	Compaction	Pass		
Seeding	Pass				

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____