

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/24/2012

Document Number:

669300092

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>212253</u>	<u>324646</u>		<u>NEIDEL, KRIS</u>

Operator Information:OGCC Operator Number: 8960 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLCAddress: 410 17TH STREET SUITE #1400City: DENVERState: COZip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
wolfe, stephen	303-882-0224	swolfe@bonanzacrk.com	operation engineer

Compliance Summary:

QtrQtr: <u>NENE</u>	Sec: <u>11</u>	Twp: <u>9N</u>	Range: <u>79W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/17/2011	200318968	MI	AC	U			Y
08/24/2010	200268861	RT	AC	S			N
08/24/2010	200268484	RT	AC	S			N
08/06/2009	200216098	RT	AC	S			N
08/04/2009	200216023	RT	AC	U			Y
12/09/2008	200200633	RT	AC	S			N
07/18/2007	200115585	RT	AC	S		P	N
07/11/2006	200093184	MI	AC	S	I	P	N
08/09/2005	200075100	RT	AC	S		P	N
08/11/2004	200058388	RT	AC	U		F	Y
08/11/2003	200042718	RT	AC	S		P	N
08/12/2002	200029603	RT	AC	S		P	N
08/02/2001	200018276	MI	AC	S		P	N
07/12/2000	200008210	RT	AC	S		P	N
09/08/1994	500143936		TA			P	N

Inspector Comment:

on location for routine UIC inspection. no equipment other than wellhead.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
212253	WELL	IJ	05/06/1996	ERIW	057-06146	MCCALLUM UNIT 85	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: NEIDEL, KRIS

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 324646

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 212253 Type: WELL API Number: 057-06146 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 880 Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: PRREB

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 08/17/2011

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: casing blew down clean water, 8 seconds.

Method of Injection: PUMP FEED

Test Type: 5 Year Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Fail
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? In Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Fail 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Fail					

Inspector Name: NEIDEL, KRIS

Compaction	Fail				
Ditches	Fail	Ditches	Fail		

S/U/V: Unsatisfactory Corrective Date: 05/01/2013

Comment: area to south of well has soil that has no growth, flow line was recently repaired. cut bank area at access road has erosion, no culverts or BMP's to prevent further erosion.

CA: Install and maintain BMP's to prevent the migration of soil.