

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
09/13/2012

Document Number:
663300564

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>424968</u>	<u>424963</u>		<u>SCHURE, KYM</u>

Operator Information:

OGCC Operator Number:	<u>10203</u>	Name of Operator:	<u>BLACK RAVEN ENERGY INC</u>
Address:	<u>1331 17TH STREET - #350</u>		
City:	<u>DENVER</u>	State:	<u>CO</u>
		Zip:	<u>80202</u>

Contact Information:

Contact Name	Phone	Email	Comment
Hataway, Billy		bhataway@blackravenenergy.com	

Compliance Summary:

QtrQtr:	<u>SESE</u>	Sec:	<u>33</u>	Twp:	<u>9N</u>	Range:	<u>43W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Inspector Comment:

Move sign to wellhead

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
424968	WELL	PR	02/27/2012		095-06343	Vieselmeyer 943-33-44	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits:	_____	Drilling Pits:	<u>1</u>	Wells:	<u>1</u>	Production Pits:	_____
Condensate Tanks:	_____	Water Tanks:	_____	Separators:	<u>1</u>	Electric Motors:	_____
Gas or Diesel Mortors:	<u>1</u>	Cavity Pumps:	_____	LACT Unit:	_____	Pump Jacks:	<u>1</u>
Electric Generators:	_____	Gas Pipeline:	<u>1</u>	Oil Pipeline:	_____	Water Pipeline:	<u>1</u>
Gas Compressors:	_____	VOC Combustor:	_____	Oil Tanks:	_____	Dehydrator Units:	_____
Multi-Well Pits:	_____	Pigging Station:	_____	Flare:	_____	Fuel Tanks:	_____

Location

Emergency Contact Number:	<u>(S/U/V)</u>	<u>Satisfactory</u>	Corrective Date:	_____
Comment:	_____			
Corrective Action:	_____			

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	<u>1</u>	<u>Satisfactory</u>			

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 424963

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 424968 Type: WELL API Number: 095-06343 Status: PR Insp. Status: PR

Producing Well

Comment: N/G well, gas meter run, no problems found

Environmental

Spills/Releases:
Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:
DWR Receipt Num: _____ Owner Name: _____ GPS : _____
Lat _____ Long _____

Field Parameters:
Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: DRY LAND
Comment: _____
1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
Guy line anchors removed? Pass CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____
1003b. Area no longer in use? Pass Production areas stabilized ? Pass

Inspector Name: SCHURE, KYM

1003c. Compacted areas have been cross ripped? In
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
Production areas have been stabilized? Pass Segregated soils have been replaced? In

RESTORATION AND REVEGETATION

Cropland

Top soil replaced In Recontoured Pass Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? I

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____