

From: [Eckman, Annie](#)
To: ["brokenbox6431@yahoo.com"](mailto:brokenbox6431@yahoo.com)
Cc: [Fischer, Alex](#); [EnviroScan, OGCC](#)
Subject: Pagoda Unit 33-34P, SENW Sec 34 T4N R 89W, API 05-107-05021, Location 316736, Remediation #7275
Date: Wednesday, September 19, 2012 1:31:34 PM

Pagoda Unit 33-34P, SENW Sec 34 T4N R 89W, API 05-107-05021, Location 316736, Remediation #7275

Mr. Wyman,

COGCC has received your Form 27 Site Investigation and Remediation Plan for the above referenced location. The Form has been approved with the following conditions (COAs):

1. Provide GPS coordinates for all of the pits;
2. Provide a diagram showing where the soil samples were collected, indicating depth of each sample;
3. Sample the area where the blow down line from the separator discharged directly into the road side ditch;
4. Provide complete laboratory analytical report, including chain-of-custody; and
5. Provide a background sample with analysis for pH and arsenic.

A copy of the approved Form 27 (document #2230334) is attached. Please refer to Remediation Project #7275 on future correspondence.

Annie Clements Eckman, PG *for*

Alex Fischer
West Environmental Supervisor



1120 Lincoln Street, Suite 801
Denver, CO 80203
Alex.fischer@state.co.us
www.cogcc.state.co.us
303.894.2100 x5138