


| | | | |
|-------------------------------|--|--|-------------|
| FORM INSP Rev 05/11 | State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109 |  | DE ET OE ES |
|-------------------------------|--|--|-------------|

Inspection Date: 09/19/2012

Document Number: 663300577

Overall Inspection: Satisfactory

FIELD INSPECTION FORM

| | | | | |
|---------------------|---------------|---------------|---------------|------------------------------------|
| Location Identifier | Facility ID | Loc ID | Tracking Type | Inspector Name: <u>SCHURE, KYM</u> |
| | <u>421377</u> | <u>421380</u> | | |

Operator Information:

OGCC Operator Number: 66190 Name of Operator: OMIMEX PETROLEUM INC

Address: 7950 JOHN T WHITE ROAD

City: FORT WORTH State: TX Zip: 76120

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|-------------------------------|---------|
| Fisher, Jeremy | 970-854-4733 | Jeremy_Fisher@omimexgroup.com | |

Compliance Summary:

QtrQtr: SWNW Sec: 26 Twp: 5N Range: 45W

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------------------------------|
| 421377 | WELL | PR | 01/26/2012 | GW | 125-11952 | Bledsoe 5-26-5-45 | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|---------------------------------|-------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: <u>1</u> | Wells: <u>1</u> | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: <u>1</u> | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: <u>1</u> |
| Electric Generators: _____ | Gas Pipeline: <u>1</u> | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|---------|---|------------|
| WELLHEAD | Unsatisfactory | | Install sign to comply with rule 210.b. | 11/14/2012 |

Emergency Contact Number: (S/U/V) Unsatisfactory Corrective Date: _____

Comment: No sign at wellhead

Corrective Action: Install sign to comply with rule 210

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|--|------|--------|-------------------|---------|
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | | | |

| Equipment: | | | | | |
|-------------------|---|-----------------------------|---------|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Gas Meter Run | 1 | Satisfactory | | | |

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| | |

| Flaring: | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 421380

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
| | | | |

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 421377 Type: WELL API Number: 125-11952 Status: PR Insp. Status: PR

Producing Well

Comment: Gas well located in irrigated field. P/W collected and injected. Gas meter run.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

- 1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
- Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
- Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? In

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? In

RESTORATION AND REVEGETATION

Cropland

Inspector Name: SCHURE, KYM

Top soil replaced In Recontoured Pass Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? I

Comment: Gas well located on cultivated cropland

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: Satisfactory Corrective Date: _____

Comment: Gas well located in irrigated field

CA: _____