



Andrews, David

045-15489

From: Jeremy Rose [jrose@magnaes.com]
Sent: Monday, September 24, 2012 8:08 AM
To: Dave Rebol (daverebol@hotmail.com); harlanhodge@hotmail.com;
steven.vencill@encana.com; Kathy highberger (dkama@kci.net); Andrews, David
Cc: aronrt@hotmail.com; nortonjr69@gmail.com; Longworth, Mike
Subject: Daily Report for Rig # 8

Follow Up Flag: Follow up
Flag Status: Flagged

DATE: 9/23/2012

OPERATOR: EnCana Oil and Gas
WELL NAME: N. Parachute EF07A-20 C29 595
COUNTY: Garfield, Colorado

5:00-7:00 Travel to location. JSA. Check fluids and start equipment.
7:00-9:00 Trip in hole and tag at 2605' (117' plug). Trip out of the hole with 85 joints of 2.375" tubing.
9:00-10:00 Trip in hole with 4 joints (110') and pump 52 sacks into 9-5/8" casing to surface. Pump 1 sack into
mouse hole.
10:00-11:00 Trip out of hole. Clean all cement equipment and prep to move.
11:00-12:00 Rig Down. Move all equipment off location and prep to move to next pad.
12:00-1:00 Repair love joy on cement truck (Loose and backing off)
1:00-2:00 Travel to Parachute, Colorado.

****All cement pumped was 15.8# Class "G" Neat with a yield of 1.15****

Tool Pusher: Jeremy Rose
Work Over Unit: Magna Energy Services Rig # 8
Cement Contractor: Magna Energy Services
Cement Supervisor: Jeremy Rose
Operations Supervisor: Steve Vencill
BLM Representative: Mike Longworth