

Andrews, David



045-15489

From: Jeremy Rose [jrose@magnaes.com]
Sent: Monday, September 24, 2012 7:20 PM
To: Dave Rebol (daverebol@hotmail.com); steven.vencill@encana.com; Kathy highberger (dkama@kci.net); Andrews, David
Cc: aronrt@hotmail.com; nortonjr69@gmail.com
Subject: Daily Report for Rig # 8

Follow Up Flag: Follow up
Flag Status: Flagged

DATE: 9/24/2012

OPERATOR: EnCana Oil and Gas
WELL NAME: N. Parachute EF07-20 C29 595
COUNTY: Garfield, Colorado

5:00-7:00 Travel to location. JSA. Check fluids and start equipment.
7:00-9:00 Call for hot work permit and receive it at 9 a.m.
9:00-10:00 Cut and remove culverts from around well.
10:00-12:00 Attempted to dig out around well head but was un able due to wells being set on a concrete pad. Stalled the back hoe out and cracked the bucket.
12:00-4:30 Called for a hydro vac. Hydro vac thought they could be on location around 1:00 p.m. but job held them up till about 4:30p.m. Hyd. Vac will complete job tonight. **Hot work permit expired**
4:30-5:30 Travel to Parachute, Colorado

Tool Pusher: Jeremy Rose
Work Over Unit: Magna Energy Services Rig # 8