



Andrews, David

From: Jeremy Rose [jrose@magnaes.com]
Sent: Wednesday, September 26, 2012 6:12 PM
To: Dave Rebol (daverebol@hotmail.com); harlanhodge@hotmail.com;
steven.vencill@encana.com; Kathy highberger (dkama@kci.net); Andrews, David
Cc: aronrt@hotmail.com; nortonjr69@gmail.com; Longworth, Mike
Subject: Daily Report for Rig # 8

DATE: 9/26/2012

OPERATOR: EnCana Oil and Gas
WELL NAME: WF02D A15 596
API #: 05-045-10780
COUNTY: Garfield, Colorado

5:00-7:00 Travel to location. JSA. Check fluids and start equipment.
7:00-9:00 Pump 103 sacks to surface into 16" conductor. Cleaned up all cement equipment.
9:00-11:00 Wait on "One call" and Ground Disturbance Permit.
11:00-12:00 Dig around well heads.
12:00-1:00 Cut casing off, weld info cap onto 16" conductor . Back fill pit.

All cement pumped was 15.8 Class "G" Neat with a yield of 1.15

Tool Pusher: Jeremy Rose
Work Over Unit: Magna Energy Services Rig # 8
Cement Contractor: Magna Energy Services
Cement Supervisor: Jeremy Rose
Operations Supervisor: Steve Vencill
BLM Representative: Mike Longworth