

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

09/10/2012

Document Number:

668400694

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|---------------|---------------|---------------|------------------------|
| Location Identifier | Facility ID | Loc ID | Tracking Type | Inspector Name: |
| | <u>230059</u> | <u>314996</u> | | <u>BROWNING, CHUCK</u> |

Operator Information:

| | | | |
|-----------------------|-----------------------|-------------------|-----------------------------------|
| OGCC Operator Number: | <u>16700</u> | Name of Operator: | <u>CHEVRON PRODUCTION COMPANY</u> |
| Address: | <u>100 CHEVRON RD</u> | | |
| City: | <u>RANGELY</u> | State: | <u>CO</u> |
| | | Zip: | <u>81648</u> |

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|-----------------------|
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |
| Peterson, Diane | 970-675-3842 | dlpe@chevron.com | Regulatory Specialist |

Compliance Summary:

| QtrQtr: | <u>NWNW</u> | Sec: | <u>23</u> | Twp: | <u>2N</u> | Range: | <u>103W</u> |
|------------|-------------|------------|-------------|------------------------------|-----------|----------------|-----------------|
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 01/13/1998 | 500157172 | PR | PR | | | | |

Inspector Comment:Wellhead w/ ESP**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------------------------------|
| 230059 | WELL | PR | 01/01/1999 | | 103-07718 | A C MCLAUGHLIN 65X | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Lease Road:**

| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|---------|-------------------|------|
| Main | Satisfactory | | | |
| Access | Satisfactory | | | |

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|---------|-------------------|---------|
| WELLHEAD | Satisfactory | | | |

Inspector Name: BROWNING, CHUCK

| | |
|--|------------------|
| Emergency Contact Number: (S/U/V) Satisfactory | Corrective Date: |
| Comment: | |
| Corrective Action: | |

| | | | | |
|--|------|--------|-------------------|---------|
| Spills: | | | | |
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| | | | | | |
|---------------------|---|-----------------------------|-----------------------------------|-------------------|---------|
| Equipment: | | | | | |
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Ancillary equipment | 1 | Satisfactory | ESP (electronic submersible pump) | | |

| | | |
|-----------------|---------|--|
| Venting: | | |
| Yes/No | Comment | |
| NO | | |

| | | | | | |
|-----------------|-----------------------------|--|---------|-------------------|---------|
| Flaring: | | | | | |
| Type | Satisfactory/Unsatisfactory | | Comment | Corrective Action | CA Date |
| | | | | | |

Predrill

Location ID: 314996

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 230059 Type: WELL API Number: 103-07718 Status: PR Insp. Status: PR

Producing Well

Comment: Well shut in at time of inspection

Environmental**Spills/Releases:**

Inspector Name: BROWNING, CHUCK

| | | |
|--|------------------------------|-------------------------------|
| Type of Spill: _____ | Description: _____ | Estimated Spill Volume: _____ |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | | |
| Corrective Action: _____ | | Date: _____ |
| Reportable: _____ | GPS: Lat _____ | Long _____ |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____ | |

| | | | |
|------------------------|-------------------|-------------|------------|
| Water Well: | | Lat _____ | Long _____ |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | |

Field Parameters:

Sample Location: _____

| | |
|--------------------------------------|--|
| Emission Control Burner (ECB): _____ | |
| Comment: _____ | |
| Pilot: _____ | Wildlife Protection Devices (fired vessels): _____ |

Reclamation - Storm Water - Pit

| | |
|--|---|
| Interim Reclamation: | |
| Date Interim Reclamation Started: _____ | Date Interim Reclamation Completed: _____ |
| Land Use: _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| 1003a. | Debris removed? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| | Waste Material Onsite? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| | Unused or unneeded equipment onsite? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| | Pit, cellars, rat holes and other bores closed? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| | Guy line anchors removed? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Guy line anchors marked? <u>Pass</u> CM _____ |
| | CA _____ CA Date _____ |
| 1003b. | Area no longer in use? <u>Pass</u> Production areas stabilized ? <u>Pass</u> |
| 1003c. | Compacted areas have been cross ripped? <u>Pass</u> |
| 1003d. | Drilling pit closed? <u>Pass</u> Subsidence over on drill pit? <u>Pass</u> |
| | Cuttings management: _____ |
| 1003e. | Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>Pass</u> |
| | Production areas have been stabilized? <u>Pass</u> Segregated soils have been replaced? _____ |
| RESTORATION AND REVEGETATION | |
| <u>Cropland</u> | |

Inspector Name: BROWNING, CHUCK

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation _____ Pass _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads _____ Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____