

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
10/11/2012

Document Number:
670200018

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>MONTOYA, JOHN</u>
	<u>245937</u>	<u>326831</u>		

Operator Information:

OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Pavelka, Linda		LPavelka@nobleenergyinc.com	

Compliance Summary:

QtrQtr: SENE Sec: 24 Twp: 4N Range: 65W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/13/2006	200096581	PR	PR	S		P	N
03/13/2000	200004972	PR	PR	S		P	N
12/17/1996	500170215	PR	PR				

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
245937	WELL	PR	03/20/2008	OG	123-13732	BURKE R G 24-8 <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____

Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____

Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____

Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____

Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____

Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			
BATTERY	Satisfactory			

Inspector Name: MONTOYA, JOHN

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Bird Protectors	2	Satisfactory			
Horizontal Heated Separator	1	Satisfactory			
Gas Meter Run	1	Satisfactory			
Emission Control Device	1	Satisfactory			
Plunger Lift	1	Satisfactory			

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST	40.297960, -104.602480

S/U/V: _____ Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action _____ Corrective Date _____

Comment _____

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	<100 BBLs	CONCRETE SUMP/VAULT	,	
S/U/V:	Comment:				
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action					Corrective Date
Comment					
Venting:					
Yes/No	Comment				
NO					
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	
Ignitor/Combustor	Satisfactory				

Predrill

Location ID: 326831

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 245937 Type: WELL API Number: 123-13732 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? Pass CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____