

Lay Limestone Of Hamilton Cliff Facing Near Hamilton Ill 2011
Acquired In Limestone Quarries



Calibration Report

Database File: sd_mld23-22cbl10912.db
Dataset Pathname: pass8
Dataset Creation: Tue Oct 09 15:02:04 2012 by Log SCH 111116

Gamma Ray Calibration Report

Serial Number:	576	
Tool Model:	1.69TEKCO	
Performed:	Mon Oct 01 07:57:11 2012	
Calibrator Value:	1.0	GAPI
Background Reading:	0.0	cps
Calibrator Reading:	1.0	cps
Sensitivity:	1.0000	GAPI/cps

Cement Bond Log Calibration Report

Serial Number:	1		
Tool Model:	3-5tekco169		
Performed:	Tue Oct 09 15:01:55 2012		
Depth:	0	ft	
Casing Diameter:	4.5	in	
	3' Spacing	5' Spacing	
Signal Zero:	1	1	mV
Calibrated Amplitude:	81.1961	81.1961	mV
Reading at Signal Zero:	0.06	0	V
Reading in Free Pipe:	2.5	2.5	V
Gain:	32.8673	32.0784	
Offset:	-0.972035	1	