

Well Completion / Workover Report						OMIMEX PETROLEUM	
Well Name: Bledsoe 5-8-3-43			Date: 8/1/12		Report # 1		
Surface Location:					API # 5-125-09184-0		
Objective:					AFE No:		
Formation:		Perforations: 2224--2250		ft KB		Coding:	
KB to Grd: ft		Perforations:		ft KB		Amount :	
PBTd : ft KB		Perforations:		ft KB		Serv. Rig start date:	
Tubing :		Csg.	Set at:	ft KB		Serv. Rig end date:	
Set at: ft KB		Packer:	Set at:	ft KB		SITP :	
Present Operation :					SICP :		
BOP Pressure Test:		Function test:	BOP Drill:	SCV :			
Operations Summary				H ₂ S (%) - 0.00		DAILY COST SUMMARY	
<p>Move on and rig up Schlumberger. Run in hole and set CIBP at 2170'. Run in hole and Dump 2 sxs cement on top of plug. Run in hole and perforate 2 shots with 3 1/8 expendable gun at 560'. Break circulation with water truck between backside of 4 1/2 and 7' casing. Well is ready to set top plugs.</p> <p>August 11, 2012 move to location. Rig up. Fill hole with 2 1/4 bbls fresh water. Mix 40 sacks of cement from Richey Redi Mix and displace with 5.1 bbls of fresh water. Wash up, rig down and move.</p> <p>8/22/12 Cut well head off 4ft below surface. Used slick line to tag cement at 281ft. Pumped cement from 50ft to surface. Used 7 sacks of cement. Washed up and moved off.</p>				Service		Item	Amount
							2,900.00
				1		DR052	1,750.00
				3		DR086	265.00
				40		cement	800.00
				7		cement	70.84
				Daily Cost:		\$5,785.84	
				Prev. Cost:			
				Cum. Cost:		\$5,785.84	
Reservoir Fluids Summary					Tubing volume : bbls		
Gas :	(Flared)	Daily: 0.00 mcf/d	Cumm: 0.00 mcf/d	Csg ann. vol : bbls			
Oil or Condensate :	(New)	Daily: 0.00 bbls	Cumm: 0.00 bbls	Open hole vol : bbls			
Water :	(New)	Daily: 0.00 bbls	Cumm: 0.00 bbls	Total : bbls			
Time Swabbed/Flowed :		Daily: 0.00 hrs.	Cumm: 0.00 hrs.	Tbg. Bottom : ft KB			
FLUIDS RECOVERED :	Type :	Oil :	bbls	Cumm:	bbls	Water :	
LOAD FLUIDS USED :	Type :	Used Today :	0.00 bbls	Rec today	0.00 bbls	To Rec. 0.00 bbls	
LOAD FLUIDS USED :	Type :	Used Today :	0.00 bbls	Rec today	0.00 bbls	To Rec. 0.00 bbls	
Equipment on location:							
Service rig hrs.:	Daily:	Cummulative :	0.00	Down:	0.00	Cummulative Downtime : 0.00 hrs	
Personnel on Location :	Rig :	Service :		Comp.		Total Personnel: 0	
Weather :	Temp:	Lease:		Roads:	Report By: Paul DeKaye	Tel no: 406-949-0050	
Reporting To:			Programmed By:				

Well Completion / Workover Report

OMIMEX CANADA LTD.

Location:

Bledsoe 5-8-3-43

Date:

1-Aug-12

Page 2 of 2