

**FORM INSP**  
Rev 05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:  
10/17/2012

Document Number:  
668500185

Overall Inspection:  
**Unsatisfactory**

**FIELD INSPECTION FORM**

|                     |               |               |               |                                          |
|---------------------|---------------|---------------|---------------|------------------------------------------|
| Location Identifier | Facility ID   | Loc ID        | Tracking Type | Inspector Name: <u>Baroumand, Soraya</u> |
|                     | <u>335973</u> | <u>335973</u> |               |                                          |

**Operator Information:**

OGCC Operator Number: 96850 Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC  
Address: 1001 17TH STREET - SUITE #1200  
City: DENVER State: CO Zip: 80202

**Contact Information:**

| Contact Name        | Phone          | Email                          | Comment            |
|---------------------|----------------|--------------------------------|--------------------|
| WESTERDALE, BARBARA |                | barbara.westerdale@state.co.us |                    |
| Shoemaker, Mike     | (970) 285-9377 | mike.shoemaker@wpxenergy.com   | Environmental Lead |
| ASH, MARGARET       |                | margaret.ash@state.co.us       |                    |
| DERANLEAU, GREG     |                | greg.deranleau@state.co.us     |                    |
| Shoemaker, Mike     | (970) 285-9377 | mike.shoemaker@wpxenergy.com   | Environmental Lead |
| STANCZYK, JANE      |                | jane.stanczyk@state.co.us      |                    |

**Compliance Summary:**

QtrQtr: SENE Sec: 12 Twp: 6S Range: 96W

**Inspector Comment:**

Inactive Built Location. 5 conductors have been set and 6 permits to drill expired in September of 2009. Surface disturbance is over 10 acres. No interim reclamation observed. Location appears to have been built in 2009. Corrective Action Required: Initiate interim reclamation per 1003 rules & submit scheduled plan by December 28, 2012. Refile expired APDs and provide notice for plans of location. Provide required sundry notices for constructed conductors per NTO "Procedures for Setting Conductor Pipe. Refer to Doc# 668500189 for inspection photos and aerials.

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name |   |
|-------------|------|--------|-------------|------------|-----------|---------------|---|
| 298639      | WELL | XX     | 09/29/2008  | LO         | 045-17304 | AP 42-12-696  | X |
| 298640      | WELL | XX     | 09/29/2008  | LO         | 045-17305 | AP 43-12-696  | X |
| 298641      | WELL | XX     | 09/29/2008  | LO         | 045-17306 | AP 443-12-696 | X |
| 298642      | WELL | XX     | 09/29/2008  | LO         | 045-17307 | AP 441-12-696 | X |
| 298643      | WELL | XX     | 09/29/2008  | LO         | 045-17308 | AP 442-12-696 | X |
| 412773      | WELL | XX     | 07/20/2009  | LO         | 045-18594 | AP 41-12-696  | X |

**Equipment:**

Location Inventory

|  |
|--|
|  |
|--|

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

Emergency Contact Number: (S/U/V) \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Spills:</b>                                         |      |        |                   |         |
|--------------------------------------------------------|------|--------|-------------------|---------|
| Type                                                   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

| <b>Venting:</b> |         |
|-----------------|---------|
| Yes/No          | Comment |
|                 |         |

| <b>Flaring:</b> |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 335973

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
|              |         |            |         |

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_  
 Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 298639 Type: WELL API Number: 045-17304 Status: XX Insp. Status: XX

Facility ID: 298640 Type: WELL API Number: 045-17305 Status: XX Insp. Status: XX

Facility ID: 298641 Type: WELL API Number: 045-17306 Status: XX Insp. Status: XX

|                     |            |                       |            |                  |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 298642 | Type: WELL | API Number: 045-17307 | Status: XX | Insp. Status: XX |
| Facility ID: 298643 | Type: WELL | API Number: 045-17308 | Status: XX | Insp. Status: XX |
| Facility ID: 412773 | Type: WELL | API Number: 045-18594 | Status: XX | Insp. Status: XX |

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment:   
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB): \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_  
 Land Use: \_\_\_\_\_  
 Comment:   
 1003a. Debris removed? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? In CM conductors remain CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

Inspector Name: Baroumand, Soraya

- 1003b. Area no longer in use? Fail Production areas stabilized? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? Fail
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003 f. Weeds Noxious weeds? P

Comment: No interim reclamation observed. Initiate interim reclamation per 1003 rules & submit scheduled plan by December 28, 2012.

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment:

Corrective Action:  Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment        |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|----------------|
| Berms            | Pass            |                         |                       |               |                          |                |
| Drains           | Pass            |                         |                       |               |                          |                |
| Rip Rap          | Pass            |                         |                       |               |                          |                |
| Ditches          | Pass            |                         |                       |               |                          | double ditches |
| Sediment Traps   | Pass            |                         |                       |               |                          |                |

Inspector Name: Baroumand, Soraya

S/U/V: Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**COGCC Comments**

| Comment                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | User     | Date       |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|
| Inactive Built Location. 5 conductors have been set and 6 permits to drill expired in September of 2009. Surface disturbance is over 10 acres. No interim reclamation observed. Location appears to have been built in 2009.<br><br>Corrective Action Required: Initiate interim reclamation per 1003 rules & submit scheduled plan by December 28, 2012. Refile expired APDs and provide notice for plans of location. Provide required sundry notices for constructed conductors per NTO "Procedures for Setting Conductor Pipe. Refer to Doc# 668500189 for inspection photos and aerials. | baroumas | 10/23/2012 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                   | URL                                                                                                                                                                 |
|--------------|-------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 668500189    | inspection photos and aerials | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3005650">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3005650</a> |