


|                               |  |  |             |
|-------------------------------|--|--|-------------|
| <b>FORM INSP</b><br>Rev 05/11 | <b>State of Colorado</b><br><b>Oil and Gas Conservation Commission</b><br>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109 |  | DE ET OE ES |
|-------------------------------|--|--|-------------|

Inspection Date: 10/23/2012

Document Number: 668200255

Overall Inspection: Satisfactory

**FIELD INSPECTION FORM**

|                     |               |               |               |                                      |
|---------------------|---------------|---------------|---------------|--------------------------------------|
| Location Identifier | Facility ID   | Loc ID        | Tracking Type | Inspector Name: <u>LEONARD, MIKE</u> |
|                     | <u>209669</u> | <u>322199</u> |               |                                      |

**Operator Information:**

OGCC Operator Number: 70385 Name of Operator: SMITH ENERGY CORP

Address: 12706 SHILOH RD

City: GREELEY State: CO Zip: 80631

**Contact Information:**

| Contact Name | Phone          | Email                   | Comment |
|--------------|----------------|-------------------------|---------|
| Smith, Glenn | (970) 381-6253 | gsmithten@what-wire.com | Owner   |

**Compliance Summary:**

QtrQtr: SWSW Sec: 16 Twp: 6S Range: 64W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 08/05/2010 | 200267296 | PR         | PR          | S                            |          |                | N               |
| 06/30/2010 | 200260013 | PR         | PR          | U                            |          |                | Y               |
| 09/13/2007 | 200124246 | PR         | PR          | U                            |          |                | Y               |
| 05/27/2002 | 200026898 | PR         | PR          | U                            |          | F              | Y               |
| 12/02/1996 | 500141625 | PR         | PR          |                              |          | F              | Y               |

**Inspector Comment:**

BERMS REPAIRED AS REQUIRED. SUBMIT TO INSPECTOR SCHEDULE FOR PAINTING SURFACE EQUIPMENT

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  |
|-------------|------|--------|-------------|------------|-----------|--|
| 209669      | WELL | PR     | 11/04/2003  | OW         | 039-06574 | RUNNING CREEK STATE 16 <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

| <b>Signs/Marker:</b> |                             |                       |                   |         |
|----------------------|-----------------------------|-----------------------|-------------------|---------|
| Type                 | Satisfactory/Unsatisfactory | Comment               | Corrective Action | CA Date |
| BATTERY              | Satisfactory                | INSTALLED AS REQUIRED |                   |         |

|          |                |                                    |                                  |            |
|----------|----------------|------------------------------------|----------------------------------|------------|
| WELLHEAD | Unsatisfactory | WELL NAME AND ID INFO BLEACHED OUT | REPIR SIGN TO MAKE INFO READABLE | 12/31/2012 |
|----------|----------------|------------------------------------|----------------------------------|------------|

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

| Type   | Area | Volume | Corrective action | CA Date |
|--|------|--------|-------------------|---------|
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

**Fencing/:**

| Type     | Satisfactory/Unsatisfactory | Comment     | Corrective Action | CA Date |
|----------|-----------------------------|-------------|-------------------|---------|
| WELLHEAD | Satisfactory                | BARBED WIRE |                   |         |

**Equipment:**

| Type                        | # | Satisfactory/Unsatisfactory | Comment                                     | Corrective Action   | CA Date    |
|-----------------------------|---|-----------------------------|---|---|------------|
| Horizontal Heated Separator | 1 | Unsatisfactory              | NO CONTENTS OR NFPA LABELS AND NEED PAINTED | INSTALL CONTENTS AND NFPA LABELING. PAINT AS REQUIRED (WHEN WEATHER ALLOWS). SUBMIT SCHEDULE TO INSPECTOR FOR BOTH REQUIREMENTS | 11/30/2012 |

**Venting:**

| Yes/No | Comment |
|--------|---------|
|        |         |

**Flaring:**

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
|      |                             |         |                   |         |

**Predrill**

Location ID: 322199

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
|              |         |            |         |

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_  
 Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 209669 Type: WELL API Number: 039-06574 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In     Temporarily Abandoned    Reminder: \_\_\_\_\_  
S/V:    Satisfactory    CA Date: \_\_\_\_\_  
CA: \_\_\_\_\_  
Comment: \_\_\_\_\_

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_  
Comment: \_\_\_\_\_  
Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_  
Land Use: \_\_\_\_\_  
Comment: \_\_\_\_\_  
1003a. Debris removed? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Waste Material Onsite? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors removed? Pass CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
1003b. Area no longer in use? Pass    Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass  
 Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: \_\_\_\_\_

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment    |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------|
| Other            | Pass            | Other                   | Pass                  |               |                          | VEGETATION |

S/U/V: Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| BERMS REPAIRED AS REQUIRED. SUBMIT TO INSPECTOR SCHEDULE FOR PAINTING SURFACE EQUIPMENT | leonardm | 10/23/2012 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 668200255    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3005714">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3005714</a> |