

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

10/22/2012

Document Number:

663901868

Overall Inspection:

Violation**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>208225</u>	<u>321852</u>		<u>QUINT, CRAIG</u>

Operator Information:

OGCC Operator Number: 72185 Name of Operator: PRODUCTION MANAGEMENT INC

Address: 5000 BUTTE ST #107

City: BOULDER State: CO Zip: 80301

Contact Information:

Contact Name	Phone	Email	Comment
Whiting, Jim	719-688-0064	jimwhiting_99@yahoo.com	
Warren, William	303-449-0557	williamwarren@hotmail.com	

Compliance Summary:

QtrQtr: <u>SWNW</u>	Sec: <u>18</u>	Twp: <u>16S</u>	Range: <u>45W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/06/2011	200310045	RT	AC	S			N
04/19/2010	200243557	RT	AC	S			N
05/19/2009	200210937	RT	AC	S			N
03/27/2008	200129468	MI	AC	S			N
04/27/2007	200109740	RT	AC	S		P	N
07/20/2006	200094586	RT	AC	S		P	N
04/26/2006	200090214	RT	AC	U		F	Y
07/29/2005	200074937	RT	AC	U		F	Y
06/24/2004	200058254	RT	AC	S		P	N
01/21/2003	200034529	MI	SI	S		P	N
04/01/1999	500140217	SR	PA		P	P	N
01/25/1999	500140216	SR	PA		F	F	Y
07/13/1998	500140219	CA	PA		F	P	N
06/11/1997	500140215	ID	TA			P	N
01/17/1996	500140218	ID	TA			F	Y
10/20/1994	500140214		TA				Y

Inspector Comment:

(Form 18, doc #200366934) Mr. Charles Mitchek (Tenant) contacted COGCC that the pumper for production Management Inc. was not using the proper access to the Coe Trust 12B-18 #2. After an inspection by COGCC inspection found that, the operator was accessing well across farm ground. Operator should contact surface owner to verify and plat proper access into well and submit to COGCC by 11/2/2012.

Related Facilities:

Inspector Name: QUINT, CRAIG

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
208225	WELL	IJ	09/24/2011	DSPW	017-07160	COE TRUST 12B-18 2	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
------	-----------------------------	---------	-------------------	---------

Predrill

Location ID: 321852

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 208225 Type: WELL API Number: 017-07160 Status: IJ Insp. Status: SI

Complaint

Comment: (Form 18, doc #200366934) Mr. Charles Mitchek (Tenant) contacted COGCC that the pumper for production Management Inc. was not using the proper access to the Coe Trust 12B-18 #2. After an inspection by COGCC inspection found that, the operator was accessing well across farm ground. Operator should contact surface owner to verify and plat proper access into well and submit to COGCC by 11/2/2012.

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Complaint:

Tracking Num	Category	Assigned To	Description	Incident Date
200366934	ACCESS	QUINT, CRAIG	Mr. Charles Mitchek (Tenant) contacted COGCC that the pumper for production Management Inc. was not using the proper access to the Coe Trust 12B-18 #2.	10/22/2012

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____ CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____ CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____ CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____ CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____ CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

Inspector Name: QUINT, CRAIG

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____