

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
10/26/2012

Document Number:
669300234

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>NEIDEL, KRIS</u>
	<u>292890</u>	<u>335897</u>		

Operator Information:

OGCC Operator Number: <u>100264</u>	Name of Operator: <u>XTO ENERGY INC</u>
Address: <u>382 CR 3100</u>	
City: <u>AZTEC</u>	State: <u>NM</u> Zip: <u>87410</u>

Contact Information:

Contact Name	Phone	Email	Comment
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field

Compliance Summary:

QtrQtr: <u>SESE</u>	Sec: <u>34</u>	Twp: <u>1S</u>	Range: <u>97W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/15/2011	200301287	MI	PD	S			N

Inspector Comment:

uic injection inspection

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
292855	WELL	PR	03/18/2011	GW	103-11090	PICEANCE CREEK UNIT 197-34B3	<input type="checkbox"/>
292858	WELL	PR	08/20/2010	GW	103-11089	PICEANCE CREEK UNIT 197-34B9	<input type="checkbox"/>
292860	WELL	PR	08/11/2010	GW	103-11088	PICEANCE CREEK UNIT 197-34B5	<input type="checkbox"/>
292871	WELL	PR	08/13/2010	GW	103-11087	PICEANCE CREEK UNIT 197-34B4	<input type="checkbox"/>
292873	WELL	PR	08/09/2010	GW	103-11086	PICEANCE CREEK UNIT 197-34B7	<input type="checkbox"/>
292887	WELL	PR	02/09/2011	LO	103-11085	PICEANCE CREEK UNIT 197-34B2	<input type="checkbox"/>
292888	WELL	PR	08/08/2010	LO	103-11084	PICEANCE CREEK UNIT 197-34B1	<input type="checkbox"/>
292889	WELL	PR	08/08/2010	LO	103-11083	PICEANCE CREEK UNIT 197-34B6	<input type="checkbox"/>
292890	WELL	IJ	09/14/2012	DSPW	103-11082	PICEANCE CREEK UNIT 197-34B8	<input checked="" type="checkbox"/>
293965	WELL	PR	08/26/2010	LO	103-11146	PICEANCE CREEK UNIT 197-34B10	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 335897

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 292890 Type: WELL API Number: 103-11082 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg 740
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____ MPP _____
Inj Zone: WSTCG

TC: Pressure or inches of Hg 0

Previous Test Pressure _____ Last MIT: 03/15/2011

Brhd: Pressure or inches of Hg 0

Previous Test Pressure _____ AnnMTRReq: _____

Comment: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____