

FORM 5A

Rev 06/12

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with columns DE, ET, OE, ES

Document Number: 400325117

Date Received: 09/10/2012

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 96850
2. Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC
3. Address: 1001 17TH STREET - SUITE #1200
City: DENVER State: CO Zip: 80202
4. Contact Name: Sandra Salazar
Phone: (303) 629-8456
Fax: (303) 629-8268

5. API Number 05-045-12861-00
6. County: GARFIELD
7. Well Name: FEDERAL
Well Number: RWF 334-9
8. Location: QtrQtr: SWSW Section: 9 Township: 6S Range: 94W Meridian: 6
9. Field Name: RULISON Field Code: 75400

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO Status: PRODUCING Treatment Type:
Treatment Date: End Date: Date of First Production this formation:
Perforations Top: 6744 Bottom: 8904 No. Holes: 135 Hole size: 0.35
Provide a brief summary of the formation treatment: Open Hole:
This formation is commingled with another formation: Yes No
Total fluid used in treatment (bbl): Max pressure during treatment (psi):
Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal):
Type of gas used in treatment: Min frac gradient (psi/ft):
Total acid used in treatment (bbl): Number of staged intervals:
Recycled water used in treatment (bbl): Flowback volume recovered (bbl):
Fresh water used in treatment (bbl): Disposition method for flowback:
Total proppant used (lbs): Rule 805 green completion techniques were utilized:
Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: Hours: Bbl oil: Mcf Gas: Bbl H2O:
Calculated 24 hour rate: Bbl oil: Mcf Gas: Bbl H2O: GOR:
Test Method: Casing PSI: Tubing PSI: Choke Size:
Gas Disposition: Gas Type: Btu Gas: API Gravity Oil:
Tubing Size: 2 + 3/8 Tubing Setting Depth: 8649 Tbg setting date: 01/25/2012 Packer Depth:

Reason for Non-Production:

Date formation Abandoned: Squeeze: Yes No If yes, number of sacks cmt 315

** Bridge Plug Depth: ** Sacks cement on top: ** Wireline and Cement Job Summary must be attached.

Comment:

The form is REVISED to report the Squeeze work done to the MV 5 at 6,750' - 6,903') w/ 125 sx 17 ppg Class G cement, drilled out cement and pressure tested squeeze holes to 1,000 psi (tested good), isolated leak in csg below MV 5 and above MV 4 after successfully pressure testing MV5 squeeze perms, squeezed csg leak w/ 190 sx 17 ppg Class G cement, pressure tested squeeze to 1,500 psi (tested good), land tbg @ 8,649' w/ 272 jts on 1/25/12, well returned to production.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Sandra Salazar

Title: Permit Technician II Date: 9/10/2012 Email sandra.salazar@wpenergy.com

Attachment Check List

Att Doc Num	Name
400325117	FORM 5A SUBMITTED
400325177	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Agency	Cement squeeze to repair casing leaks.	11/7/2012 11:32:31 AM

Total: 1 comment(s)