

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
11/16/2012

Document Number:
663300776

Overall Inspection:
Unsatisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>SCHURE, KYM</u>
	<u>237656</u>	<u>317274</u>		

Operator Information:

OGCC Operator Number: 24320 Name of Operator: DIAMOND OPERATING, INC.
 Address: 6666 GUNPARK DR STE #200
 City: BOULDER State: CO Zip: 80301

Contact Information:

Contact Name	Phone	Email	Comment
Peterson, Dave	303-494-4420	davep@flatironenergy.com	

Compliance Summary:

QtrQtr: SENE Sec: 20 Twp: 2S Range: 53W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/06/2010	200277633	SR	PR	S	I		N
08/12/2010	200272028	PR	PR	U			Y
11/01/2007	200121561	PR	PR	S			N
10/15/1998	500159851	ES	PR			P	N
05/13/1996	500159850	PR	PR			P	N
12/05/1995	500159849	PR	PR			P	N
09/20/1995	500159848	PR	PR			F	Y

Inspector Comment:

Unlined skim pit Operator is communicating with COGCC regarding compliance.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
237656	WELL	PR	02/28/1985	OW	121-10159	IDEA 1

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____
 Comment: _____

Inspector Name: SCHURE, KYM

Corrective Action:

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 317274

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 237656 Type: WELL API Number: 121-10159 Status: PR Insp. Status: PR

Producing Well

Comment: Unlined skim pit violation

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____
 Comment: _____

- 1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
- Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
- Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
- Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: SCHURE, KYM

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits:

Pit Type: Skimming/Settling Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Unlined skim pit violation

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Pit (S/U/V): **Violation** Comment: Remove/remediate/line skim pit or replace with tank and remove/remediate existing skim pit.

Corrective Action: Remove/remediate/line skim pit or replace with tank and remove/remediate existing skim pit.

Date: **03/15/2013**