

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
11/06/2012

Document Number:
669400232

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>LABOWSKIE, STEVE</u>
	<u>215995</u>	<u>326176</u>		

Operator Information:

OGCC Operator Number: <u>10000</u>	Name of Operator: <u>BP AMERICA PRODUCTION COMPANY</u>
Address: <u>501 WESTLAKE PARK BLVD</u>	
City: <u>HOUSTON</u>	State: <u>TX</u> Zip: <u>77079</u>

Contact Information:

Contact Name	Phone	Email	Comment
Best, Julie	(970) 375-7540/ (970) 394-0131	julie.best@bp.com	Environmental Advisor
Fauth, Dan	(970) 749-4238	daniel.fauth@bp.com	Environmental Advisor (Durango)
Kerr, Kyle	(970) 382-3690/ (970) 317-0623	kyle.kerr@bp.com	Environmental Advisor

Compliance Summary:

QtrQtr: <u>NWSW</u>	Sec: <u>10</u>	Twp: <u>32N</u>	Range: <u>6W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/19/2011	200302486	PR	PR	S			N
11/17/2010	200284396	PR	PR	S			N
10/01/2008	200196160	PR	PR	S			N
11/08/2006	200107555	PR	PR	S		P	N
09/30/2005	200079678	PR	PR	S		P	N
11/05/2003	200049305	PR	PR	S		P	N
09/18/2002	200032191	PR	PR	S		P	N
09/18/2000	200010305	PR	PR	S		P	N
12/02/1999	200002990	PR	PR	S		P	N
09/14/1998	500149902	PR	PR			P	N
01/27/1997	500149901	PR	PR			P	N
07/07/1995	500149900	PR	PR				N
01/10/1995	500149899	CO					

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
215995	WELL	PR	09/15/1994	GW	067-07601	BAKER GAS UNIT32-6-10 1 <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
OTHER		minor stuffing box leak on pumping unit, may need attention soon if gets any worse.		

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
OTHER	Satisfactory	panels around all equipment		
PUMP JACK	Satisfactory	stock panels		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ancillary equipment	1	Satisfactory			
Prime Mover	1	Satisfactory			
Horizontal Heated Separator	1	Satisfactory			
Bird Protectors	1	Satisfactory			
Pump Jack	1	Satisfactory	inactive, taken apart, minor stuffing box leak		
Gas Meter Run	1	Satisfactory			
Deadman # & Marked	4	Satisfactory	SW anchor down		

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 326176

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 215995 Type: WELL API Number: 067-07601 Status: PR Insp. Status: PR

Producing Well

Comment:

Environmental

Spills/Releases:
 Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____
 Lat _____ Long _____

Field Parameters:

 Sample Location:

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment:

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment:

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
Berms	Pass					run-on control

S/U/V: Unsatisfactory Corrective Date: 04/01/2013

Comment: irrigation ditch close by, shale soil/bedrock, high erosion area, large erosoion channel on southwest corner. Pad has good gravel and compaction but ersoion is occurring in interim area and pad is affecting flow.

CA: Evaluate ersoion due to stormwater flow off and around pad. Additional erosion control BMPs may be necessary.