

FORM
5
Rev
02/08

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:
2287121

Date Received:
01/23/2012

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type Final completion Preliminary completion

1. OGCC Operator Number: 100185 4. Contact Name: SHEILLA REED-HIGH
2. Name of Operator: ENCANA OIL & GAS (USA) INC Phone: (720) 876-3678
3. Address: 370 17TH ST STE 1700 Fax: (720) 876-4678
City: DENVER State: CO Zip: 80202-

5. API Number 05-123-33111-00 6. County: WELD
7. Well Name: ARISTOCRAT ANGUS Well Number: 4-0-3
8. Location: QtrQtr: LOT 3 Section: 3 Township: 3N Range: 65W Meridian: 6
Footage at surface: Distance: 875 feet Direction: FNL Distance: 2108 feet Direction: FWL
As Drilled Latitude: _____ As Drilled Longitude: _____

GPS Data:

Data of Measurement: _____ PDOP Reading: _____ GPS Instrument Operator's Name: _____

** If directional footage at Top of Prod. Zone Dist.: 94 feet. Direction: FNL Dist.: 2573 feet. Direction: FWL
Sec: 3 Twp: 3N Rng: 65W

** If directional footage at Bottom Hole Dist.: 95 feet. Direction: FNL Dist.: 2584 feet. Direction: FWL
Sec: 3 Twp: 3N Rng: 65W

9. Field Name: WATTENBERG 10. Field Number: 90750
11. Federal, Indian or State Lease Number: _____

12. Spud Date: (when the 1st bit hit the dirt) 11/21/2011 13. Date TD: 11/26/2011 14. Date Casing Set or D&A: 11/27/2011

15. Well Classification:

Dry Oil Gas/Coalbed Disposal Stratigraphic Enhanced Recovery Storage Observation

16. Total Depth MD 7805 TVD** 7704 17 Plug Back Total Depth MD 7728 TVD** 7627

18. Elevations GR 4765 KB 4777

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:

CBL, DUAL IND/COMPENSATED DENSITY/COMPENSATED NEUTRON

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
SURF	12+1/4	8+5/8	24	0	629	255	0	629	CALC
1ST	7+7/8	4+1/2	11.6	0	7,790	605	3,300	7,790	CBL

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES					
FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
SUSSEX	4,422		<input type="checkbox"/>	<input type="checkbox"/>	
NIOBRARA	6,914		<input type="checkbox"/>	<input type="checkbox"/>	
CODELL	7,190		<input type="checkbox"/>	<input type="checkbox"/>	
J SAND	7,643		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: SHEILLA REED-HIGH

Title: DRILLING & COMP. TECH Date: 1/6/2012 Email: SHEILLA.REEDHIGH@ENCANA.COM

Attachment Check List

Att Doc Num	Document Name	attached ?	
<u>Attachment Checklist</u>			
2287123	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2287122	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<u>Other Attachments</u>			
2287121	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

General Comments

User Group	Comment	Comment Date
Permit	Directional survey correct. ok to pass.	11/8/2012 1:27:10 PM
Permit	Directional Survey doesn't match drilling data. Also no DS data is attached. Notified opr and put form on hold.	5/1/2012 3:40:02 PM

Total: 2 comment(s)