

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

10/30/2012

Document Number:

665400560

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|---------------|---------------|---------------|--------------------|
| Location Identifier | Facility ID | Loc ID | Tracking Type | Inspector Name: |
| | <u>220255</u> | <u>312263</u> | | <u>PRECUP, JIM</u> |

Operator Information:

OGCC Operator Number: 95620 Name of Operator: WESTERN OPERATING COMPANY

Address: 518 17TH ST STE 200

City: DENVER State: CO Zip: 80202

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|----------------------------|---------|
| James, Steven | (303) 893-2438 | s.d.james@att.net | |
| ONYSKIW, DENISE | | denise.onyskiw@state.co.us | |

Compliance Summary:

| QtrQtr: | <u>SENE</u> | Sec: | <u>34</u> | Twp: | <u>9N</u> | Range: | <u>54W</u> |
|------------|-------------|------------|-------------|------------------------------|-----------|----------------|-----------------|
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 06/16/2011 | 200312784 | MI | SI | S | | | N |
| 08/25/2010 | 200268732 | SR | AC | S | I | | N |
| 07/26/2010 | 200263872 | RT | AC | U | | | N |
| 11/05/2009 | 200221554 | MI | AC | S | | | N |
| 06/30/2009 | 200214058 | RT | SI | S | | | N |
| 04/08/2008 | 200130227 | RT | AC | S | | | N |
| 08/15/2007 | 200117884 | RT | AC | S | | | N |
| 04/01/2006 | 200094778 | MI | SI | S | | P | N |
| 08/17/2005 | 200075983 | RT | AC | S | | P | N |
| 05/10/2004 | 200054419 | MI | SI | S | | P | N |
| 01/23/2004 | 200049000 | PR | SI | U | | F | Y |
| 01/11/1996 | 500153519 | PR | PR | | | P | N |
| 08/28/1995 | 500153518 | PR | PR | | | P | N |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------------------------------|
| 220255 | WELL | SI | 06/09/2009 | ERIW | 075-08377 | EMERALD 8-34 | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

Inspector Name: PRECUP, JIM

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|-------------------------------------|----------------------------|------------|
| Access | Unsatisfactory | no access to lease road --wired out | provide access to wellhead | 12/14/2012 |

Signs/Marker:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|---------|-------------------|---------|
| WELLHEAD | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Venting:

| Yes/No | Comment |
|--------|---------|
| NO | |

Flaring:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 312263

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 220255 Type: WELL API Number: 075-08377 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 06/16/2011

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: flowline to tubing on wellhead--no guages--not plumbed to surface pipe--sign and shed on wellhead--passes routine UIC

Method of Injection: GRAVITY FEED _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Fail CM not all anchors marked properly
 CA properly mark anchors CA Date 11/20/2012

1003b. Area no longer in use? _____ Production areas stabilized? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATIONCropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | Ditches | Pass | CM | Pass | |

Inspector Name: PRECUP, JIM

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____