

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/11/2012

Document Number:

663400019

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>242616</u>	<u>318970</u>		<u>MONTOYA, JOHN</u>

Operator Information:

OGCC Operator Number: 47120 Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Contact Information:

Contact Name	Phone	Email	Comment
Pavelka, Linda		LPavelka@nobleenergyinc.com	

Compliance Summary:

QtrQtr: SENE Sec: 27 Twp: 5N Range: 64W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/03/2004	200053858	PR	PR	S		P	N
01/07/1998	500165572	PR	PR				

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
242616	WELL	PR	05/10/2012	OW	123-10407	HUNTER 1	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
WELLHEAD	Satisfactory			
CONTAINERS	Satisfactory			
TANK LABELS/PLACARDS				

Inspector Name: MONTOYA, JOHN

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
IGNITOR/COMBUST OR	Satisfactory			
WELLHEAD	Satisfactory			

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Emission Control Device	1	Satisfactory			
Bird Protectors	3	Satisfactory			
Horizontal Heated Separator	1	Satisfactory			
Plunger Lift	1	Satisfactory			
Gas Meter Run	1	Satisfactory			

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST	40.223950,-104.317940

S/U/V: _____

Comment: _____

Corrective Action: _____

Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	Corrective Date
-------------------	-----------------

Comment

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ignitor/Combustor	Satisfactory			

Predrill

Location ID: 318970

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 242616 Type: WELL API Number: 123-10407 Status: PR Insp. Status: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: MONTOYA, JOHN

Comment: <input style="width:700px" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
Field Parameters:			
<input style="width:300px" type="text"/>			
Sample Location: <input style="width:400px" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit

Interim Reclamation:			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: _____			
Comment: <input style="width:700px" type="text"/>			
1003a.	Debris removed? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Waste Material Onsite? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Unused or unneeded equipment onsite? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Pit, cellars, rat holes and other bores closed? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Guy line anchors removed? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Guy line anchors marked? _____ CM _____		
	CA _____	CA Date _____	
1003b.	Area no longer in use? <u>Pass</u>	Production areas stabilized ? <u>Pass</u>	
1003c. Compacted areas have been cross ripped? _____			
1003d. Drilling pit closed? <u>Pass</u> Subsidence over on drill pit? <u>Pass</u>			
Cuttings management: _____			
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>Pass</u>			
	Production areas have been stabilized? <u>Pass</u>	Segregated soils have been replaced? <u>Pass</u>	
RESTORATION AND REVEGETATION			
<u>Cropland</u>			
	Top soil replaced <u>Pass</u>	Recontoured <u>Pass</u>	Perennial forage re-established <u>Pass</u>

Inspector Name: MONTOYA, JOHN

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____