

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
12/11/2012

Document Number:
668400840

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	288226	334527		BROWNING, CHUCK

Operator Information:

OGCC Operator Number:	<u>66561</u>	Name of Operator:	<u>OXY USA INC</u>
Address:	<u>PO BOX 27757</u>		
City:	<u>HOUSTON</u>	State:	<u>TX</u>
		Zip:	<u>77227</u>

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Chris	970-263-3651	chris_clark@oxy.com	Field Regulatory Lead-Piceance
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Compliance Summary:

QtrQtr:	<u>SESW</u>	Sec:	<u>16</u>	Twp:	<u>9S</u>	Range:	<u>94W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/11/2011	200325758	PR	PR	S			N
08/24/2011	200327270	PR	PR	S			N
09/03/2010	200270918	ES	PR	S			N
03/02/2010	200234835	PR	PR	S			N

Inspector Comment:

8-Wellheads, 1-quintuple and 1-triple separator, 3-400 bbl steel tanks w/ metal berms. Pigging station on N side of pad. Telemetry tower.9 abandoned locations associated w/ pad. Pits closed and area stabilized.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
126	WELL	PR	09/16/2008	GW	077-09477	CURREY 16-15C	X
127	WELL	PR	08/06/2008	GW	077-09478	CURREY 21-2A	X
128	WELL	PR	03/17/2009	GW	077-09479	CURREY 16-15B	X
288220	WELL	AL	01/04/2008	LO	077-09202	CURREY 21-4	
288221	WELL	PR	04/23/2012	GW	077-09201	CURREY 21-2	X
288222	WELL	PR	01/13/2011	GW	077-09200	CURREY 16-15	X
288224	WELL	PR	05/07/2012	GW	077-09199	CURREY 16-14	X
288226	WELL	PR	09/18/2008	OW	077-09198	CURREY 16-11	X
294212	WELL	PR	03/17/2009	GW	077-09469	CURREY 16-15A	X
296108	WELL	AL	05/15/2012	LO	077-09645	Currey 16-14A	
296109	WELL	AL	05/15/2012	LO	077-09643	Currey 21-2C	
296110	WELL	AL	05/15/2012	LO	077-09642	Currey 21-2B	
296111	WELL	AL	05/15/2012	LO	077-09641	Currey 16-14B	
296112	WELL	AL	05/15/2012	LO	077-09640	Currey 16-11C	

296113	WELL	AL	05/15/2012	LO	077-09639	Currey 16-11B	
296114	WELL	AL	05/15/2012	LO	077-09638	Currey 16-11A	
297656	WELL	AL	05/15/2012	LO	077-09704	Currey 16-14C	

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			
Main	Satisfactory			

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Pig Station	1	Satisfactory			
Horizontal Heated Separator	8	Satisfactory			

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	3	400 BBLS	STEEL AST	39.271770,-107.888000	
S/U/V:	Satisfactory	Comment:			
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
NO					
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 334527

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 126 Type: WELL API Number: 077-09477 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 127 Type: WELL API Number: 077-09478 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 128 Type: WELL API Number: 077-09479 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 288221 Type: WELL API Number: 077-09201 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 288222 Type: WELL API Number: 077-09200 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 288224 Type: WELL API Number: 077-09199 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 288226 Type: WELL API Number: 077-09198 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 294212 Type: WELL API Number: 077-09469 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS: _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

- 1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
- Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Inspector Name: BROWNING, CHUCK

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	MHSP	Pass	

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____