

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/13/2012

Document Number:

668400845

Overall Inspection:

Violation**FIELD INSPECTION FORM**

Location Identifier Facility ID Loc ID Tracking Type Inspector Name: BROWNING, CHUCK

228643 314397

Operator Information:

OGCC Operator Number: 16700 Name of Operator: CHEVRON PRODUCTION COMPANY

Address: 100 CHEVRON RD

City: RANGELY State: CO Zip: 81648

Contact Information:

Contact Name	Phone	Email	Comment
KOEHLER, BOB		bob.koehler@state.co.us	
Peterson, Diane	970-675-3842	dlpe@chevron.com	Regulatory Specialist
ONYSKIW, DENISE		denise.onyskiw@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Compliance Summary:

QtrQtr: SWSW Sec: 30 Twp: 2N Range: 102W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/31/2012	659300129	IJ	SI	V			Y
05/18/2011	200311320	RT	AC	S			N
05/18/2010	200258849	RT	AC	S			N
06/10/2009	200213902	RT	AC	S			N
12/11/2008	200199982	RT	AC	S			N
05/14/2007	200111691	RT	AC	S		P	N
05/16/2006	200091869	RT	AC	S		P	N
05/27/2005	200071759	RT	AC	S		P	N
05/04/2004	200055921	MI		S		P	N
05/28/2003	200042618	RT	AC	S		P	N
05/17/2002	200026689	RT	AC	S		P	N
05/24/2001	200018479	RT	AC	S		P	N
05/30/2000	200008938	RT	AC	S		P	N

Inspector Comment:

WELL REPAIRED FOR CASING LEAK.RETEST FAILED TO HOLD PRESSURE.SEE ATTACHED NOAV DOC#200372004

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
228643	WELL	IJ	01/01/1999	DSPW	103-05599	EMERALD 3	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Inspector Name: BROWNING, CHUCK

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			
Main	Satisfactory			

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment
NO	

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 314397

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 228643 Type: WELL API Number: 103-05599 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: WEBR

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 02/19/2007

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Method of Injection: _____

Test Type: Verification of Repairs Tbg psi: 0 Csg psi: 1200 BH psi: 0

Insp. Status: Fail Leak Type: _____

Comment: WELL REPAIRED FOR CASING LEAK.
 RETEST FAILED TO HOLD PRESSURE.
 SEE NOAV DOC#200372004

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass CM _____

CA _____ CA Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass1003d. Drilling pit closed? PassSubsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? PassProduction areas have been stabilized? Pass

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	MHSP	Pass	

Inspector Name: BROWNING, CHUCK

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668400846	NOAV200372004	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3031896