

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

12/17/2012

Document Number:

663800628

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

|                     |               |               |               |                        |
|---------------------|---------------|---------------|---------------|------------------------|
| Location Identifier | Facility ID   | Loc ID        | Tracking Type | Inspector Name:        |
|                     | <u>270070</u> | <u>334901</u> |               | <u>LONGWORTH, MIKE</u> |

**Operator Information:**OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

| Contact Name     | Phone        | Email                        | Comment |
|------------------|--------------|------------------------------|---------|
| Contact, General | 970-285-2665 | cogcc.inspections@encana.com |         |

**Compliance Summary:**QtrQtr: SWNE Sec: 32 Twp: 6S Range: 92W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 06/04/2007 | 200113876 | PR         | PR          | S                            | I        | P              | N               |
| 06/23/2006 | 200098869 | PR         | PR          | S                            | I        | P              | N               |
| 03/17/2005 | 200069238 | PR         | PR          | S                            |          | P              | N               |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name           |                                     |
|-------------|------|--------|-------------|------------|-----------|-------------------------|-------------------------------------|
| 270069      | WELL | PR     | 09/07/2004  | GW         | 045-09447 | SHIDELER 32-2D (G32NEC) | <input checked="" type="checkbox"/> |
| 270070      | WELL | PR     | 04/26/2004  | GW         | 045-09446 | SHIDELER 32-8C (G32NEC) | <input checked="" type="checkbox"/> |

**Equipment:****Location Inventory**

|                             |                        |                     |                         |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____     | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____  | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____      | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____      | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location****Lease Road:**

| Type   | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|---------|-------------------|------|
| Access | Satisfactory                |         |                   |      |

Inspector Name: LONGWORTH, MIKE

| <b>Signs/Marker:</b> |                             |         |                   |         |
|----------------------|-----------------------------|---------|-------------------|---------|
| Type                 | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD             | Satisfactory                |         |                   |         |
| BATTERY              | Satisfactory                |         |                   |         |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

| <b>Good Housekeeping:</b> |                             |         |                   |         |
|---------------------------|-----------------------------|---------|-------------------|---------|
| Type                      | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WEEDS                     | Satisfactory                |         |                   |         |
| TRASH                     | Satisfactory                |         |                   |         |

| <b>Spills:</b> |      |        |                   |         |
|----------------|------|--------|-------------------|---------|
| Type           | Area | Volume | Corrective action | CA Date |

☐ Multiple Spills and Releases?

| <b>Equipment:</b>           |   |                             |         |                   |         |
|-----------------------------|---|-----------------------------|---------|-------------------|---------|
| Type                        | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Deadman # & Marked          | 3 | Satisfactory                |         |                   |         |
| Bird Protectors             | 1 | Satisfactory                |         |                   |         |
| Horizontal Heated Separator | 2 | Satisfactory                |         |                   |         |
| Plunger Lift                | 2 | Satisfactory                |         |                   |         |

| <b>Venting:</b> |         |  |
|-----------------|---------|--|
| Yes/No          | Comment |  |
|                 |         |  |

| <b>Flaring:</b> |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 334901

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:**

|              |         |            |         |
|--------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
|              |         |            |         |

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 270069 Type: WELL API Number: 045-09447 Status: PR Insp. Status: PR

**Producing Well**

Comment: \_\_\_\_\_

Facility ID: 270070 Type: WELL API Number: 045-09446 Status: PR Insp. Status: PR

**Producing Well**Comment: **Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: 

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**Sample Location: 

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: 1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? In Production areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass1003d. Drilling pit closed? Pass Subsidence over on drill pit? \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation In Process

#### Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation Multi-Well Location ☐

#### Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches          | Pass            |                         |                       |               |                          |         |
| Retention Ponds  | Pass            |                         |                       |               |                          |         |
| Compaction       | Pass            |                         |                       |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
| Seeding          |                 |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |

S/U/V: Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_