

FORM
5Rev
02/08**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400352554

Date Received:

11/30/2012

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type ☒ Final completion ☐ Preliminary completion

1. OGCC Operator Number: 100185

4. Contact Name: Marina Ayala

2. Name of Operator: ENCANA OIL & GAS (USA) INC

Phone: (720) 876-5905

3. Address: 370 17TH ST STE 1700

Fax: (720) 876-6905

City: DENVER State: CO Zip: 80202-

5. API Number 05-045-20295-00

6. County: GARFIELD

7. Well Name: N. Parachute

Well Number: EF16D-27 P27595

8. Location: QtrQtr: SESE Section: 27 Township: 5S Range: 95W Meridian: 6

Footage at surface: Distance: 659 feet Direction: FSL Distance: 562 feet Direction: FEL

As Drilled Latitude: 39.579384 As Drilled Longitude: -108.033219

GPS Data:

Date of Measurement: 11/14/2011 PDOP Reading: 4.0 GPS Instrument Operator's Name: Ben Johnson

** If directional footage at Top of Prod. Zone Dist.: 603 feet. Direction: FSL Dist.: 663 feet. Direction: FEL

Sec: 27 Twp: 5S Rng: 95W

** If directional footage at Bottom Hole Dist.: 596 feet. Direction: FSL Dist.: 686 feet. Direction: FEL

Sec: 27 Twp: 5S Rng: 95W

9. Field Name: GRAND VALLEY

10. Field Number: 31290

11. Federal, Indian or State Lease Number:

12. Spud Date: (when the 1st bit hit the dirt) 02/08/2012 13. Date TD: 05/09/2012 14. Date Casing Set or D&A: 05/10/2012

15. Well Classification:

☐ Dry ☐ Oil ☒ Gas/Coalbed ☐ Disposal ☐ Stratigraphic ☐ Enhanced Recovery ☐ Storage ☐ Observation

16. Total Depth MD 10155 TVD** 10151 17 Plug Back Total Depth MD 10103 TVD** 10098

18. Elevations GR 6650 KB 6669

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:

CBL and Mud.

20. Casing, Liner and Cement:

CASING

| Casing Type | Size of Hole | Size of Casing | Wt/Ft | Csg/Liner Top | Setting Depth | Sacks Cmt | Cmt Top | Cmt Bot | Status |
|-------------|--------------|----------------|-------|---------------|---------------|-----------|---------|---------|--------|
| CONDUCTOR | 26 | 16 | 42 | 0 | 118 | 394 | 0 | 118 | CALC |
| SURF | 12+1/4 | 9+5/8 | 36 | 0 | 1,819 | 431 | 0 | 1,819 | CALC |
| 1ST | 8+3/4 | 4+1/2 | 11.6 | 0 | 10,127 | 1,367 | 2,270 | 10,155 | CBL |

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

| Method used | String | Cementing tool setting/perf depth | Cement volume | Cement top | Cement bottom |
|-------------|--------|-----------------------------------|---------------|------------|---------------|
| | | | | | |

Details of work:

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES

| FORMATION NAME | Measured Depth | | Check if applies | | COMMENTS (All DST and Core Analyses must be submitted to COGCC) |
|----------------|----------------|--------|--------------------------|--------------------------|---|
| | Top | Bottom | DST | Cored | |
| WILLIAMS FORK | 6,518 | 10,014 | <input type="checkbox"/> | <input type="checkbox"/> | |
| ROLLINS | 10,015 | 10,155 | <input type="checkbox"/> | <input type="checkbox"/> | |

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Marina Ayala

Title: Permitting Technician Date: 11/30/2012 Email: marina.ayala@encana.com

Attachment Check List

| Att Doc Num | Document Name | attached ? | | | |
|-----------------------------|-----------------------|------------|-------------------------------------|----|-------------------------------------|
| <u>Attachment Checklist</u> | | | | | |
| 2113904 | CMT Summary * | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> |
| | Core Analysis | Yes | <input type="checkbox"/> | No | <input checked="" type="checkbox"/> |
| 400352568 | Directional Survey ** | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> |
| | DST Analysis | Yes | <input type="checkbox"/> | No | <input checked="" type="checkbox"/> |
| | Logs | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> |
| | Other | Yes | <input type="checkbox"/> | No | <input checked="" type="checkbox"/> |
| <u>Other Attachments</u> | | | | | |
| 400352554 | FORM 5 SUBMITTED | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> |
| 400352555 | MUD | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> |
| 400352560 | MUD | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> |
| 400352569 | DIRECTIONAL DATA | Yes | <input checked="" type="checkbox"/> | No | <input type="checkbox"/> |

General Comments

| User Group | Comment | Comment Date |
|------------|--|---------------------------|
| Permit | Received and attached surface cement job summary. | 1/3/2013 7:43:37 AM |
| Permit | Directional Survey attached. Still WO Surface Cement Summary. | 12/20/2012 10:05:54 AM |
| Permit | ON HOLD: Requesting dir sur, cement summary on surface pipe. CBL equivalent is doc # 2317818. Requested cement summary again. 12/24/12 | 12/11/2012 1:06:21 PM |

Total: 3 comment(s)