

2011 Aerial image of Retta J #1 well pad



5/30/12 Photo of well pad taken to SE from access road



5/30/12 Photo taken of pad from above southwest corner, taken to NE



5/30/12 Photo of run-on control ditch on west side of pad taken to S.





5/30/12 Photo of fill slope and erosion control on north side of pad taken to E.



5/30/12 Photo of east fill slope of pad, taken to N.





5/30/12 Stormwater control cut into native soil at NE corner of pad.



5/30/12 Detail of landfill contents exposed in cut shown above.





5/30/12 Photo taken of unstabilized cut slope and “run-on” control ditch on south edge of pad



5/30/12 Photo of discharge for “run-on” control ditches

