

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
01/14/2013

Document Number:
663800684

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

| | | | | |
|---------------------|---------------|---------------|---------------|--|
| Location Identifier | Facility ID | Loc ID | Tracking Type | Inspector Name: <u>LONGWORTH, MIKE</u> |
| | <u>290321</u> | <u>334342</u> | | |

Operator Information:

| | |
|--|---|
| OGCC Operator Number: <u>100322</u> | Name of Operator: <u>NOBLE ENERGY INC</u> |
| Address: <u>1625 BROADWAY STE 2200</u> | |
| City: <u>DENVER</u> | State: <u>CO</u> Zip: <u>80202</u> |

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|----------------------------|--------------|
| Bruner, Ryan | (303) 228-4158 | rbruner@nobleenergyinc.com | Enviromental |

Compliance Summary:

| QtrQtr: <u>NESW</u> | Sec: <u>2</u> | Twp: <u>8S</u> | Range: <u>96W</u> | | | | |
|---------------------|---------------|----------------|-------------------|------------------------------|----------|----------------|-----------------|
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 06/07/2010 | 200286705 | PR | PR | S | | | N |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------------------------------|
| 279080 | WELL | PR | 10/05/2010 | GW | 045-10994 | HYRUP 2-46 | <input checked="" type="checkbox"/> |
| 290316 | WELL | PR | 01/07/2011 | GW | 045-14073 | HYRUP 2-23A | <input checked="" type="checkbox"/> |
| 290317 | WELL | PR | 05/01/2012 | GW | 045-14072 | HYRUP 2-23B | <input checked="" type="checkbox"/> |
| 290318 | WELL | PR | 12/01/2010 | GW | 045-14071 | HYRUP 2-23C | <input checked="" type="checkbox"/> |
| 290319 | WELL | PR | 04/30/2010 | GW | 045-14070 | HYRUP 2-24A | <input checked="" type="checkbox"/> |
| 290320 | WELL | PR | 08/01/2011 | GW | 045-14069 | HYRUP 2-24B | <input checked="" type="checkbox"/> |
| 290321 | WELL | PR | 04/30/2010 | GW | 045-14068 | HYRUP 2-33A | <input checked="" type="checkbox"/> |
| 290536 | WELL | PR | 03/01/2010 | GW | 045-14132 | HYRUP 2-24C | <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Lease Road: | | | | |
|--------------------|-----------------------------|--|-------------------|------|
| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
| Access | Satisfactory | Snow packed deep snow between ruts. Plowing again would be nice. | | |

| Signs/Marker: | | | | |
|----------------------|-----------------------------|---|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | Satisfactory | Labeled Sour Condensate / Sour Produced Water | | |
| BATTERY | Satisfactory | | | |
| CONTAINERS | Satisfactory | | | |
| WELLHEAD | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

| Good Housekeeping: | | | | |
|---------------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| TRASH | Satisfactory | | | |

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| TANK BATTERY | Satisfactory | | | |
| SEPARATOR | Satisfactory | | | |
| WELLHEAD | Satisfactory | | | |

| Equipment: | | | | | |
|-----------------------------|---|-----------------------------|-------------------|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Bird Protectors | 4 | Satisfactory | | | |
| Horizontal Heated Separator | 8 | Satisfactory | 2 quad separators | | |
| Plunger Lift | 8 | Satisfactory | | | |

| | | | | | |
|--------------------|-----------------------------|-----------------------------------|---------------------|----------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | | |
| Contents | # | Capacity | Type | SE GPS | |
| CONDENSATE | 4 | 300 BBLS | STEEL AST | 39.376270,108.072140 | |
| S/U/V: | Satisfactory | Comment: | | | |
| Corrective Action: | | | | Corrective Date: | |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | _____ | | | | |
| Other (Capacity) | _____ | | | | |
| Other (Type) | _____ | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Venting: | | | | | |
| Yes/No | Comment | | | | |
| | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date | |
| | | | | | |

Predrill

Location ID: 334342

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
| | | | |

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 279080 Type: WELL API Number: 045-10994 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 290316 Type: WELL API Number: 045-14073 Status: PR Insp. Status: PR

Producing Well

Comment:

Facility ID: 290317 Type: WELL API Number: 045-14072 Status: PR Insp. Status: PR

Producing Well

Comment:

Facility ID: 290318 Type: WELL API Number: 045-14071 Status: PR Insp. Status: PR

Producing Well

Comment:

Facility ID: 290319 Type: WELL API Number: 045-14070 Status: PR Insp. Status: PR

Producing Well

Comment:

Facility ID: 290320 Type: WELL API Number: 045-14069 Status: PR Insp. Status: PR

Producing Well

Comment:

Facility ID: 290321 Type: WELL API Number: 045-14068 Status: PR Insp. Status: PR

Producing Well

Comment:

Facility ID: 290536 Type: WELL API Number: 045-14132 Status: PR Insp. Status: PR

Producing Well

Comment:

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment:
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

- 1003a. Debris removed? Pass CM _____ CA _____ CA Date _____
Waste Material Onsite? Pass CM _____ CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____ CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____ CA _____ CA Date _____
Guy line anchors removed? Pass CM _____ CA _____ CA Date _____
Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? In _____ Production areas stabilized? Pass _____

1003c. Compacted areas have been cross ripped? Pass _____

1003d. Drilling pit closed? Pass _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P _____

Comment: _____

Overall Interim Reclamation In Process _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Inspector Name: LONGWORTH, MIKE

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |
| Berms | Pass | Berms | Pass | MHSP | Pass | |
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Ditches | Pass | | | |
| Seeding | | Culverts | Pass | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____