

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

01/18/2013

Document Number:

668600250

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>208518</u>	<u>321918</u>		<u>QUINT, CRAIG</u>

Operator Information:OGCC Operator Number: 74250 Name of Operator: RESOURCE DEVELOPMENT TECHNOLOGY LLCAddress: 7175 W JEFFERSON STE 1200City: LAKEWOOD State: CO Zip: 80235**Contact Information:**

Contact Name	Phone	Email	Comment
Bowman, Tom	303-716-3200	tombowman@usermail.com	
Pelton, Shane	719-767-8987 off	spelton62@yahoo.com	719-340-8987 cell

Compliance Summary:QtrQtr: SWNE Sec: 12 Twp: 14S Range: 45W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/11/2011	663900071	IJ	PA	S	P		N
07/22/2011	200316349	RT	SI	U			Y
08/24/2010	200267926	RT	AC	S			N
04/19/2010	200243549	RT	AC	U			Y
05/14/2009	200210319	RT	AC	S			N
05/14/2008	200189924	RT	AC	S			N
03/28/2007	200108071	RT	AC	S		P	N
05/16/2006	200090427	MI	SI	S		P	N
09/21/2005	200079124	MI	AC	U		F	Y
07/28/2005	200074923	RT	AC	S		P	N
07/28/2004	200058112	RT	AC	S		P	N
08/19/2003	200043321	RT	AC	S		P	N
07/31/2002	200029502	RT	AC	S		P	N
08/20/2001	200019525	RT	AC	S		P	N
09/22/2000	200010812	MI	AC	S	I	P	N
08/29/2000	200009362	MI	SI	U	I	F	Y
05/19/1999	500140781	PR	AC			P	N
11/05/1997	500140780	PR	AC			P	N
06/13/1996	500140779	PR	AC			P	Y
06/27/1995	500140778	DG	WO			P	Y

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name		
208518	WELL	PA	11/11/2011		017-07453	SMITH 1B	<input checked="" type="checkbox"/>	

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	ELEVATED GRAVEL ROAD THROUGH PASTURE.		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory	LEASE SIGN MOUNTED ON STAIRS		
TANK LABELS/PLACARDS	Unsatisfactory	LABELING HAS PEELED OFF OF TANKS	Install sign to comply with rule 210.d.	04/18/2013

Emergency Contact Number: (S/U/V) Unsatisfactory

Corrective Date: 04/18/2013

Comment: NO EMERGENCY NUMBERS

Corrective Action: INSTALL EMERGENCY NUMBERS

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory	STEEL PANELS AROUND TANKS.		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ancillary equipment		Satisfactory			

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	2	400 BBLS	FIBERGLASS AST	38.849970,-102.395680	
S/U/V:	Satisfactory		Comment: _____		
Corrective Action:				Corrective Date:	
Paint					
Condition	_____				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment _____					
Venting:					
Yes/No		Comment			
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 321918

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 208518 Type: WELL API Number: 017-07453 Status: PA Insp. Status: PA

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: QUINT, CRAIG

Comment: <input style="width:700px" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
Field Parameters:			
<input style="width:300px" type="text"/>			
Sample Location: <input style="width:400px" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Inspector Name: QUINT, CRAIG

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass

Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured Fail

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed Fail

Locations, facilities, roads, recontoured Fail

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% Fail

Cropland: perennial forage _____

Weeds present Pass

Subsidence In

Comment: TANK BATTERY STILL IN PLACE, 1-TANK WITH MANHOLE COVER REMOVED.

Corrective Action: REMOVE TANKS AND RECLAIM LOCATION OR REDESIGNATE FACILITY.

Date 04/18/2013

Overall Final Reclamation Fail

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____