FORM INSP Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM

DE	ET	OE	ES

Inspection Date: 01/23/2013

Document Number: 668600275

Overall Inspection: Satisfactory

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	207828	321708		QUINT, CRAIG

Operator Information:

OGCC Operator Number: 17180 Name of Operator: CITATION OIL & GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77269

Contact Information:

Contact Name	Phone	Email	Comment
ELSOM, LEE ANN	281-891-1577 EXT 1577	lelsom@cogc.com	
Kennedy, Hershel	719-767-8851 off	hkennedy@cogc.com	719-340-1150 cell

Compliance Summary:

QtrQtr: SENW Sec: 31 Twp: 14S Range: 41W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/07/2011	200326326	PR	PR	S			N
01/08/2010	200226543	PR	PR	S			N
01/24/2007	200103165	PR	PR	S		P	N
03/27/2001	200015975	PR	PR	S	I	P	N
07/02/1999	948167	PR	PR	S		P	N
08/29/1997	500139336	PR	PR			P	N
05/08/1996	500139335	PR	PR			P	N
05/01/1995	500139334	PR	PR			P	Y

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
207828	WELL	PR	12/01/1989	OW	017-06763	ARAPAHOE UNIT 122(22-31)	X

Equipment:

Location Inventory

Special Purpose Pits:		Drilling Pits:		Wells:		Production Pits:	
Condensate Tanks:		Water Tanks:		Separators:		Electric Motors:	
Gas or Diesel Mortors:		Cavity Pumps:		LACT Unit:		Pump Jacks:	
Electric Generators:		Gas Pipeline:		Oil Pipeline:		Water Pipeline:	
Gas Compressors:		VOC Combustor:		Oil Tanks:		Dehydrator Units:	
Multi-Well Pits:		Pigging Station:		Flare:		Fuel Tanks:	

Location

Inspector Name: QUINT, CRAIG

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	GRAVEL ROAD THROUGH FARM GROUND		

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory	STICKERS ON TANKS		
BATTERY	Satisfactory	BATTERY SIGN BY TANKS		
WELLHEAD	Satisfactory	LEASE SIGN BY WELLHEAD		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date:

Comment:

Corrective Action:

Spills:				
Type	Area	Volume	Corrective action	CA Date

☐ Multilple Spills and Releases?

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	STEEL PANELS AROUND WELLHEAD AND UNIT		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ancillary equipment	5	Satisfactory	OIL SALES PUMP, WATER PUMP IN SHED BY TANK, TELEMETRY EQUIPMENT, ELEC PANEL, CATHOTIC RECTIFIER.		
Prime Mover	1	Satisfactory	ELEC MOTOR		
Pump Jack	1	Satisfactory	LUFKIN 228 LOW PROFILE IN A WOODEN CELLAR		
Gas Meter Run	1	Satisfactory			
Veritcal Heater Treater	2	Satisfactory	WITH SHEDS		

Inspector Name: QUINT, CRAIG

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	400 BBLS	FIBERGLASS AST	38.790050,-102.052760

S/U/V:	Satisfactory	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate

Corrective Action		Corrective Date	
Comment			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST	38.789760,-102.052780

S/U/V:	Satisfactory	Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Insufficient	Adequate

Corrective Action		Corrective Date	
Comment	WILL NEED ATTENTION SOON		

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 321708

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment:

CA: **Date:**

Wildlife BMPs:

Comment:

CA: **Date:**

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
			`

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 207828 Type: WELL API Number: 017-06763 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING, CENTRAL BATTERY F/(AU 121, 122) 1900' W @ 38.78976, -102.05278

Environmental

Spills/Releases:

Inspector Name: QUINT, CRAIG

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Inspector Name: QUINT, CRAIG

Top soil replaced Pass Recontoured Pass Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION ARE FARMED.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/U/V: Satisfactory Corrective Date: _____

Comment:

CA: