

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
02/07/2013

Document Number:
668400914

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>228634</u>	<u>314390</u>		<u>BROWNING, CHUCK</u>

Operator Information:

OGCC Operator Number:	<u>16700</u>	Name of Operator:	<u>CHEVRON PRODUCTION COMPANY</u>
Address:	<u>100 CHEVRON RD</u>		
City:	<u>RANGELY</u>	State:	<u>CO</u>
		Zip:	<u>81648</u>

Contact Information:

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	Regulatory Specialist
ONYSKIW, DENISE		denise.onyskiw@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Compliance Summary:

QtrQtr:	<u>NESE</u>	Sec:	<u>26</u>	Twp:	<u>2N</u>	Range:	<u>103W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/24/2012	668400413	IJ	AC	S			N
08/15/2011	200318345	MI	AC	S			N
05/17/2010	200254421	RT	AC	S			N
06/09/2009	200213625	RT	AC	S			N
05/15/2008	200192252	MT	AC	S			N
05/14/2007	200111686	RT	AC	S		P	N
05/16/2006	200091864	RT	AC	S		P	N
05/12/2005	200071754	RT	AC	S		P	N
05/10/2004	200055847	RT		S		P	N
05/20/2003	200042614	RT	AC	S		P	N
05/15/2002	200026692	RT	AC	S		P	N
05/23/2001	200018474	RT	AC	S		P	N
05/24/2000	200008931	MI	AC	S		P	N

Inspector Comment:

UIC-MIT. Pressure well to 1200 psi . Hold for 15 min. Final pressure 1200 psi. -0 psi loss. OKSee Form 21 Doc# 01171436

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
228634	WELL	IJ	01/01/1999	DSPW	103-05590	EMERALD 8	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			
Main	Satisfactory			

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 314390

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 228634 Type: WELL API Number: 103-05590 Status: IJ Insp. Status: AC

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____

MPP _____

Inj Zone: WEBR

TC: Pressure or inches of Hg _____

Previous Test Pressure _____

Last MIT: 08/15/2011

Brhd: Pressure or inches of Hg _____

Previous Test Pressure _____

AnnMTReq: _____

Comment: _____

Method of Injection: _____

Test Type: Verification of Repairs

Tbg psi: 0

Csg psi: 1200

BH psi: 0

Insp. Status: Pass

Comment: UIC. Pressure well to 1200 psi . Hold for 15 min. Final pressure 1200 psi. -0 psi loss. OK
See Form 21 Doc# 01171436

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	MHSP	Pass	

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____