

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/15/2013

Document Number:

667601143

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>250998</u>	<u>336616</u>		<u>HICKEY, MIKE</u>

Operator Information:

OGCC Operator Number: 47120 Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Contact Information:

Contact Name	Phone	Email	Comment
Avant, Paul	720-929-6457	Paul.Avant@anadarko.com	
Cocciolone, Ashley	720-929-6625	Ashley.Cocciolone@anadarko.com	

Compliance Summary:

QtrQtr: NWNW Sec: 8 Twp: 3N Range: 66W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/18/2007	200110677	BH	PR	S		P	N
03/11/2002	200024837	PR	PR	S		P	N
06/06/1997	500178195	PR	PR				
12/30/1994	500178194	DG	DG			P	N

Inspector Comment:

Routine inspection of API #05-123-18801, HSR- Tuttle #4-8 et al multi-well location.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
250998	WELL	PR	06/06/2004	GW	123-18801	HSR-TUTTLE 4-8	X
289096	WELL	PR	04/04/2010	OW	123-24739	BELLA FEDERAL 41-7	X
414523	WELL	PR	04/06/2010	OW	123-30774	BELLA 21-8	X
414540	WELL	PR	04/05/2010	OW	123-30780	BELLA 22-8	X

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>4</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>4</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: <u>1</u>	VOC Combustor: <u>1</u>	Oil Tanks: <u>4</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: <u>3</u>

Location

Inspector Name: HICKEY, MIKE

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
WELLHEAD	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
SEPARATOR	Satisfactory			
WELLHEAD	Satisfactory	X4		
TANK BATTERY	Satisfactory			
IGNITOR/COMBUST OR	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	4				
Horizontal Heated Separator	2	Satisfactory			
Emission Control Device	1	Satisfactory			
Compressor	1	Satisfactory			
Bird Protectors	3	Satisfactory			
Gas Meter Run	1	Satisfactory			

Inspector Name: HICKEY, MIKE

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Corrective Action				Corrective Date	
Comment					
Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CRUDE OIL	3	300 BBLS	STEEL AST	40.244130,104.806920	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	
Ignitor/Combustor	Satisfactory				

Predrill

Location ID: 336616

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 250998 Type: WELL API Number: 123-18801 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 289096 Type: WELL API Number: 123-24739 Status: PR Insp. Status: PR

Inspector Name: HICKEY, MIKE

Producing Well

Comment:

Facility ID: 414523 Type: WELL API Number: 123-30774 Status: PR Insp. Status: PR

Producing Well

Comment:

Facility ID: 414540 Type: WELL API Number: 123-30780 Status: PR Insp. Status: PR

Producing Well

Comment:

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment:

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

Inspector Name: HICKEY, MIKE

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established In

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____

