

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

01/03/2013

Document Number:

668500261

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: Baroumand, Soraya
	291763	334450		

Operator Information:OGCC Operator Number: 10433 Name of Operator: PICEANCE ENERGY LLCAddress: 1512 LARIMER STREET #1000City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Natvig, Randy	303-339-4337	Rnatvig@laramie-energy.com	Drilling and Completions Manager
Bankert, Wayne	970-812-5310	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Compliance Summary:QtrQtr: SWSE Sec: 27 Twp: 9S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/12/2010	200287064	PR	PR	S			N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
290616	WELL	PR	11/13/2012	GW	077-09289	NORTH VEGA 27-341	<input checked="" type="checkbox"/>
291284	WELL	PR	07/09/2007	GW	077-09323	DLC 27-241	<input checked="" type="checkbox"/>
291350	WELL	PR	07/10/2007	GW	077-09322	DLC 27-331	<input checked="" type="checkbox"/>
291353	WELL	PR	07/10/2007	GW	077-09321	DLC 27-441	<input checked="" type="checkbox"/>
291755	WELL	PR	08/07/2007	GW	077-09371	DLC 27-244	<input checked="" type="checkbox"/>
291763	WELL	PR	08/07/2007	GW	077-09375	DLC 27-234	<input checked="" type="checkbox"/>
291764	WELL	PR	08/07/2007	GW	077-09374	DLC 27-344	<input checked="" type="checkbox"/>
291765	WELL	PR	08/07/2007	GW	077-09373	DLC 27-444	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Inspector Name: Baroumand, Soraya

Emergency Contact Number: (S/U/V) <u>Unsatisfactory</u>	Corrective Date: <u>04/30/2013</u>
Comment: <u>signs need updated emergency contact numbers</u>	
Corrective Action: <u>Provide emergency contact information and phone number(s) on sign at which the operator can be reached at all times per rule 210.b.2.</u>	

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Heated Separator	8	Satisfactory	2-quad unit		
Bird Protectors		Satisfactory			
Emission Control Device	1	Satisfactory			

Facilities: <input type="checkbox"/> New Tank Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	5	400 BBLs	STEEL AST	,	
S/U/V:	Satisfactory	Comment:			
Corrective Action:				Corrective Date:	

Paint	
Condition	Inadequate
Other (Content) _____	
Other (Capacity) _____	
Other (Type) _____	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 334450

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 290616 Type: WELL API Number: 077-09289 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Facility ID: 291284 Type: WELL API Number: 077-09323 Status: PR Insp. Status: PR

Inspector Name: Baroumand, Soraya

Producing Well

Comment: producing

Facility ID: 291350 Type: WELL API Number: 077-09322 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Facility ID: 291353 Type: WELL API Number: 077-09321 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Facility ID: 291755 Type: WELL API Number: 077-09371 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Facility ID: 291763 Type: WELL API Number: 077-09375 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Facility ID: 291764 Type: WELL API Number: 077-09374 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Facility ID: 291765 Type: WELL API Number: 077-09373 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? Pass1003c. Compacted areas have been cross ripped? In1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? InProduction areas have been stabilized? Pass Segregated soils have been replaced? In**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced In Recontoured In 80% Revegetation In1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Inspector Name: Baroumand, Soraya

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Berms	Pass					
Gradient Terraces	Pass					

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____