

FORM
5

Rev
02/08

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400379173

Date Received:

02/08/2013

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type Final completion Preliminary completion

1. OGCC Operator Number: 100322 4. Contact Name: EILEEN ROBERTS
 2. Name of Operator: NOBLE ENERGY INC Phone: (303) 2284330
 3. Address: 1625 BROADWAY STE 2200 Fax: (303) 2284286
 City: DENVER State: CO Zip: 80202

5. API Number 05-123-34389-00 6. County: WELD
 7. Well Name: SCHMIDT PC C Well Number: 06-69HC
 8. Location: QtrQtr: SESE Section: 36 Township: 5N Range: 65W Meridian: 6
 Footage at surface: Distance: 556 feet Direction: FSL Distance: 651 feet Direction: FEL
 As Drilled Latitude: 40.349950 As Drilled Longitude: -104.604380

GPS Data:

Date of Measurement: 04/18/2012 PDOP Reading: 3.2 GPS Instrument Operator's Name: Paul Tappy

** If directional footage at Top of Prod. Zone Dist.: 75 feet. Direction: FNL Dist.: 570 feet. Direction: FWL

Sec: 6 Twp: 4N Rng: 64W

** If directional footage at Bottom Hole Dist.: 88 feet. Direction: FNL Dist.: 535 feet. Direction: FEL

Sec: 6 Twp: 4N Rng: 64W

9. Field Name: WATTENBERG 10. Field Number: 90750

11. Federal, Indian or State Lease Number: _____

12. Spud Date: (when the 1st bit hit the dirt) 03/06/2012 13. Date TD: 03/16/2012 14. Date Casing Set or D&A: 03/16/2012

15. Well Classification:

Dry Oil Gas/Coalbed Disposal Stratigraphic Enhanced Recovery Storage Observation

16. Total Depth MD 11492 TVD** 6919 17 Plug Back Total Depth MD 11442 TVD** 6869

18. Elevations GR 4775 KB 4788

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:

CBL/GRL/CCL/VDL.

No other logs sent at this time.

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	18+1/2	16+0/0	84.00	24	124	80	0	124	CALC
SURF	13+3/4	9+5/8	36.00	24	750	404	0	760	CALC
1ST	8+3/4	7+0/0	26.00	24	7,384	565	1,850	7,394	CBL
1ST LINER	6+1/8	4+1/2	11.60	7253	11,444				

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
PIERRE	2,800		<input type="checkbox"/>	<input type="checkbox"/>	
PARKMAN	3,850		<input type="checkbox"/>	<input type="checkbox"/>	
SUSSEX	4,349		<input type="checkbox"/>	<input type="checkbox"/>	
SHANNON	4,905		<input type="checkbox"/>	<input type="checkbox"/>	
NIOBRARA	6,901		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Eileen Roberts

Title: Regulatory Specialist Date: 2/8/2013 Email: eroberts@nobleenergyinc.com

Attachment Check List

Att Doc Num	Document Name	attached ?	
<u>Attachment Checklist</u>			
400379221	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2113942	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<u>Other Attachments</u>			
400379173	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400379217	CEMENT BOND	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400379224	DIRECTIONAL DATA	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

General Comments

User Group	Comment	Comment Date
Permit	Operator concurred that TPZ is in section 6, not 31. Ready to pass.	2/14/2013 8:04:24 AM
Permit	Top and side views received and attached as second Directional Survey attachment.	2/13/2013 2:58:18 PM
Permit	On hold. Directional Survey is missing top and side views. TPZ footage should be in section 6 4N 64W, not 36 5N 65W.	2/13/2013 8:56:57 AM

Total: 3 comment(s)