

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

03/01/2013

Document Number:

663800790

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>294638</u>	<u>335005</u>		<u>LONGWORTH, MIKE</u>

Operator Information:OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Insp., General	970-285-2665	cogcc.inspections@encana.com	

Compliance Summary:QtrQtr: SWSW Sec: 19 Twp: 7S Range: 95W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
290563	WELL	PR	08/07/2008	GW	045-14139	FEDERAL 19-12(PM19)	<input checked="" type="checkbox"/>
294636	WELL	PR	07/19/2008	GW	045-15541	FEDERAL 19-12BB (PM-19)	<input checked="" type="checkbox"/>
294637	WELL	PR	07/26/2008	GW	045-15542	FEDERAL 19-14 (PM-19)	<input checked="" type="checkbox"/>
294638	WELL	PR	08/04/2008	GW	045-15543	FEDERAL 19-11BB (PM-19)	<input checked="" type="checkbox"/>
294639	WELL	PR	07/21/2008	GW	045-15544	FEDERAL 19-13 (PM-19)	<input checked="" type="checkbox"/>
294640	WELL	PR	08/04/2008	GW	045-15545	FEDERAL 19-13BB (PM-19)	<input checked="" type="checkbox"/>
294641	WELL	PR	08/03/2008	GW	045-15546	FEDERAL 19-11 (PM-19)	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	Gated entrance		

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory	@ separators		
WELLHEAD	Satisfactory	no legal discription on well tags		
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	Unsatisfactory	Unused pipe and baracade by the gathering line	Remove unused equipment	03/30/2013
STORAGE OF SUPL	Unsatisfactory	Trash bin @ south east corner	Remove trash bin	03/30/2013

Spills:				
Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Unsatisfactory	4 strand barb wire. Fencing by the east side of gate is down	Repair fence	03/30/2013

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Bird Protectors	2	Satisfactory	1 per unit		
Horizontal Heated Separator	7	Unsatisfactory	1 double and a 5 unit separator. No berms around separators.	build a berm around separators	05/03/2013
Deadman # & Marked		Unsatisfactory		Mark or remove deadmen	03/30/2013
Plunger Lift	7	Satisfactory			
Gathering Line	1	Satisfactory			
Gas Meter Run	1	Satisfactory			

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	4	300 BBLS	STEEL AST	39.418690,108.046500	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No		Comment			
YES		4 vents on tanks/ 1 per tank			
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 335005

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 290563 Type: WELL API Number: 045-14139 Status: PR Insp. Status: PR

Producing Well

Comment: PR well

Facility ID: 294636 Type: WELL API Number: 045-15541 Status: PR Insp. Status: PR

Producing Well

Comment: PR well

Facility ID: 294637 Type: WELL API Number: 045-15542 Status: PR Insp. Status: PR

Producing Well

Comment: PR well

Facility ID: 294638 Type: WELL API Number: 045-15543 Status: PR Insp. Status: PR

Producing Well

Comment: PR well

Facility ID: 294639 Type: WELL API Number: 045-15544 Status: PR Insp. Status: PR

Producing Well

Comment: PR well

Facility ID: 294640 Type: WELL API Number: 045-15545 Status: PR Insp. Status: PR

Producing Well

Comment: PR well

Facility ID: 294641 Type: WELL API Number: 045-15546 Status: PR Insp. Status: PR

Producing Well

Comment: PR well

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Complaint:				
Tracking Num	Category	Assigned To	Description	Incident Date
200321718	ODOR	SPRY OROURKE, LINDA	CDPHE Incident 2011-0688. Caller was awakened with with marked itching of the skin of her face and arms, involving the parts that were outside of the covers. She noted that there was a brown cloud in the sky 1/4 - 1/2 mile southeast of her house. She went outside and took a picture of it. She did not note any associated odor. The stars and moon were also visible. This morning when she awakened, she noted that the brown cloud was gone. She has noted this brown cloud one other time, but it is not usually present. She has spoken with the Encana representative listed above about other concerns related to this well. The well is located on the other side of Stone Quarry Road from her house.	09/20/2011

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Fail CM Trash binCA Remove trash bin CA Date 03/30/2013Unused or unneeded equipment onsite? Fail CM unused pipe and baracade @ gathering lineCA Remove all unused equipment CA Date 03/30/2013Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? Fail CM _____CA Remove or mark CA Date 03/30/2013Guy line anchors marked? Fail CM _____CA Remove or mark CA Date 03/30/20131003b. Area no longer in use? In Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: LONGWORTH, MIKE

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation _____ Fail _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads _____ Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Blankets	Pass	Compaction	Pass			
Compaction	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Hydro Mulch	Pass	Rip Rap	Pass			
Slope Roughening	Pass	Seeding	Pass			
Gravel	Pass	Gravel	Pass			
Berms	Pass	Berms	Pass	MHSP	Pass	tank battery

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
663800790	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3070108