



File Name: 2120_dda_03-27-2013-01

Parachute Valley Gathering System Release, Project #2120

Date: 03-27-2013

Photographer: David Andrews

Facing: northwest

Description: View of Parachute Creek, looking upstream at precautionary absorbent booms.



File Name: 2120_dda_03-27-2013-02

Parachute Valley Gathering System Release, Project #2120

Date: 03-27-2013

Photographer: David Andrews

Facing: northwest

Description: Staff gauge in Parachute Creek, just downstream of pipeline ROW crossing; No visual indications of impact in creek.



File Name: 2120_dda_03-27-2013-03

Parachute Valley Gathering System Release, Project #2120

Date: 03-27-2013

Photographer: David Andrews

Facing: northwest

Description: Newly installed above-ground protective covers on groundwater monitoring wells; interceptor trench and vacuum truck on right.



File Name: 2120_dda_03-27-2013-04

Parachute Valley Gathering System Release, Project #2120

Date: 03-27-2013

Photographer: David Andrews

Facing: north-northeast

Description: Monitoring well drilling rig, rigged down and ready to demobilize.