

FORM
INSPRev
05/11

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

03/29/2013

Document Number:

670500731

Overall Inspection:

Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	426820	426836	MONTOYA, JOHN	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER

State: CO

Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Pavelka, Linda	303-506-4592	LPavelka@nobleenergyinc.com	

Compliance Summary:

QtrQtr: NWNW Sec: 8 Twp: 5N Range: 62W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
426790	WELL	PR	09/12/2012	LO	123-34780	WELLS RANCH AF08-68-1HN	<input type="checkbox"/>
426820	WELL	PR	12/13/2012	LO	123-34791	WELLS RANCH AF08-69-1HN	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits:	Drilling Pits:	Wells:	2	Production Pits:
Condensate Tanks:	Water Tanks:	6	Separators:	4
Gas or Diesel Mortors:	Cavity Pumps:	LACT Unit:		Pump Jacks:
Electric Generators:	Gas Pipeline:	1	Oil Pipeline:	2
Gas Compressors:	VOC Combustor:	2	Oil Tanks:	16
Multi-Well Pits:	Pigging Station:		Flare:	
				Fuel Tanks:

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 426836

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:**

BMP Type	Comment
Storm Water/Erosion Control	Stormwater management plans (SWMP) are in place to address construction, drilling and operations associated with Oil & Gas development throughout the state of Colorado in accordance with Colorado Department of Public Health and Environment (CDPHE) General Permit No. COR-038637. BMP's will be constructed around the perimeter of the site prior to, or at the beginning of construction. BMP's used will vary according to the location, and will remain in place until the pad reaches final reclamation.
General Housekeeping	Housekeeping will consist of neat and orderly storage of materials and fluids. Wastes will be temporarily stored in sealed containers and regularly collected and disposed of at offsite, suitable facilities. If spills occur prompt cleanup is required to minimize any commingling of waste materials with stormwater runoff. Routine maintenance will be limited to fueling and lubrication of equipment. Drip pans will be used during routine fueling and maintenance to contain spills or leaks. Any waste product from maintenance will be containerized and transported offsite for disposal or recycling. There will be no major equipment overhauls conducted onsite. Equipment will be transported offsite for major overhauls. Cleanup of trash and discarded materials will be conducted at the end of each work day. Cleanup will consist of patrolling the roadway, access areas, and other work areas to pickup trash, scrap debris, other discarded materials, and any contaminated soil. These materials will be disposed of properly.
Material Handling and Spill Prevention	Spill Prevention Control and Countermeasures (SPCC) plans are in place to address any possible spill associated with Oil & Gas operations throughout the state of Colorado in accordance with CFR 112.

Comment: _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

Inspector Name: MONTOYA, JOHN

Corrective Action: _____		Date: _____	
Comments: Erosion BMPs: _____			
Other BMPs: _____			
Comment: _____			
Staking: _____			
On Site Inspection (305):			
<u>Surface Owner Contact Information:</u>			
Name: _____		Address: _____	
Phone Number: _____		Cell Phone: _____	
<u>Operator Rep. Contact Information:</u>			
Landman Name: _____		Phone Number: _____	
Date Onsite Request Received: _____		Date of Rule 306 Consultation: _____	
Request LGD Attendance: _____			
<u>LGD Contact Information:</u>			
Name: _____		Phone Number: _____	
		Agreed to Attend: _____	
<u>Summary of Landowner Issues:</u>			
<u>Summary of Operator Response to Landowner Issues:</u>			
<u>Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:</u>			

Facility

Facility ID: 426820	Type: WELL	API Number: 123-34791	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: producing

Environmental

Spills/Releases:

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:

		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? _____ P _____

Comment: _____

Overall Interim Reclamation Pass**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Inspector Name: MONTOYA, JOHN

Debris removed _____ No disturbance /Location never built _____
Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____
Comment: _____
Corrective Action: _____ Date _____

Overall Final Reclamation

Multi-Well Location



Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____
CA: _____