


FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
-------------------------------	--	--	----------------------

Inspection Date:
03/14/2013

Document Number:
669400483

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID <u>295911</u>	Loc ID <u>334281</u>	Inspector Name: <u>LABOWSKIE, STEVE</u>	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
---------------------	------------------------------	-------------------------	--	---	-------------------

Operator Information:

OGCC Operator Number: 10000 Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 501 WESTLAKE PARK BLVD

City: HOUSTON State: TX Zip: 77079

Contact Information:

Contact Name	Phone	Email	Comment
Best, Julie	(970) 375-7540/ (970) 394-0131	julie.best@bp.com	Environmental Advisor
Fauth, Dan	(970) 749-4238	daniel.fauth@bp.com	Environmental Advisor (Durango)
Kerr, Kyle	(970) 382-3690/ (970) 317-0623	kyle.kerr@bp.com	Environmental Advisor

Compliance Summary:

QtrQtr: NWSW Sec: 13 Twp: 34N Range: 9W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/08/2011	200304925	PR	PR	S			N
10/24/2008	200197863	PR	PR	S			N
07/31/2008	200193494	ES	WO	S			N

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
215964	WELL	PR	09/24/1990	GW	067-07570	LELAND HILL GAS UNIT 'A' 1	X
259556	WELL	PR	04/13/2005	GW	067-08413	HILL LELAND GAS UNIT A 2	X
295864	WELL	PR	05/02/2008	GW	067-09552	HILL LELAND GU A 3	X
295911	WELL	PR	05/07/2008	GW	067-09557	HILL LELAND GU A 4	X

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
OTHER		all other equipment fenced with stock panels		
WELLHEAD		stock panels at wellhead/around pumping units		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	4	Satisfactory	in 3 sheds		
Ancillary equipment	3	Satisfactory	telemetry		
Prime Mover	4	Satisfactory	elec., elec./hydraulic		
Pump Jack	3	Satisfactory			
Progressive Cavity	1	Satisfactory			
Deadman # & Marked	5	Satisfactory			
Ancillary equipment	2	Satisfactory	AC transformers		
Bird Protectors	4	Satisfactory			
Vertical Heated Separator	4	Satisfactory			
Flow Line	4	Satisfactory			

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL	37.190220,-107.782940
S/U/V:	Satisfactory		Comment:	
Corrective Action:				Corrective Date:
<u>Paint</u>				
Condition	Adequate			
Other (Content)	_____			
Other (Capacity)	95 bbl			
Other (Type)	_____			
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL	37.190360,-107.783380
S/U/V:	Satisfactory		Comment:	
Corrective Action:				Corrective Date:
<u>Paint</u>				
Condition	Adequate			
Other (Content)	_____			
Other (Capacity)	21 bbl			
Other (Type)	_____			
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

--

Predrill

Location ID: 334281

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 215964 Type: WELL API Number: 067-07570 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 259556 Type: WELL API Number: 067-08413 Status: PR Insp. Status: PR

Producing Well

Comment:

Facility ID: 295864 Type: WELL API Number: 067-09552 Status: PR Insp. Status: PR

Producing Well

Comment:

Facility ID: 295911 Type: WELL API Number: 067-09557 Status: PR Insp. Status: PR

Producing Well

Comment:

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass CM _____

CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003 f. Weeds Noxious weeds? P

Comment:

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Gravel	Pass	Ditches	Pass			

Inspector Name: LABOWSKIE, STEVE

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____