

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
04/18/2013

Document Number:
668600641

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	<u>212645</u>	<u>324793</u>	<u>QUINT, CRAIG</u>	2A Doc Num:	

Operator Information:

OGCC Operator Number: 16520 Name of Operator: CHEMCO INC
 Address: 558 CASTLE PINES PKWY UTB4#402
 City: CASTLE ROCK State: CO Zip: 80104

Contact Information:

Contact Name	Phone	Email	Comment
Neher, Gray	303-771-7777	bogray@msn.com	
ONYSKIW, DENISE		denise.onyskiw@state.co.us	
LEONARD, MIKE		mike.leonard@state.co.us	

Compliance Summary:

QtrQtr: SWSE Sec: 10 Twp: 19S Range: 45W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/04/2013	668600600	IJ	AC	V			Y
05/06/2011	200310052	RT	AC	S			N
06/29/2010	200261190	SR	AO	S			N
04/12/2010	200242415	RT	AC	S			N
06/17/2009	200213260	RT	AC	S			N
06/16/2008	200191049	MI	AC	S			N
04/06/2007	200108903	RT	AC	S		P	N
07/05/2006	200094294	RT	AC	S		P	N
07/26/2005	200074868	RT	AC	S		P	N
07/30/2004	200058095	RT	AC	S		P	N
08/20/2003	200043205	MI	AC	S		P	N
07/25/2002	200029486	RT	AC	S		P	N
08/21/2001	200019519	RT	AC	S		P	N
08/28/2000	200009368	RT	AC	S	I	P	N
04/07/2000	200011615	PR	AC	S	I	P	N
08/13/1998	500144480	PR	AC			P	N
10/18/1995	500144479	PR	AC			P	Y
11/09/1993	500144478		AC				

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
212645	WELL	IJ	11/10/1992	OW	061-06005	LINCOLN 1	X

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	SIGN BY WELL		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	STEEL PANELS TAKEN DOWN FOR WORKOVER.		

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 324793

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 212645 Type: WELL API Number: 061-06005 Status: IJ Insp. Status: SI

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____
(e.g. 30 psig or -30" Hg)

Previous Test Pressure _____

MPP _____

Inj Zone: MSSP

TC: Pressure or inches of Hg _____

Previous Test Pressure _____

Last MIT: 06/16/2008

Brhd: Pressure or inches of Hg _____

Previous Test Pressure _____

AnnMTReq: YES

Comment: _____

Method of Injection: GRAVITY FEED

Test Type: Verification of Repairs

Tbg psi: 0

Csg psi: 0

BH psi: _____

Insp. Status: Pass

Comment: REPAIRED WELL, REMOVED OLD CSG PATCH, CSG LEAK BETWEEN 1690' - 2080', CONSOLIDATED SQUEEZED 125 SX CLASS A CMT. RIG UP EXTREME HEAT, PRESSURE CASING TO 350 PSIG, 5 MIN-340#, 10 MIN-340#, 15 MIN-340#, -10# PRES LOSS (PASS). INJECTION CAN RESUME.

Workover

Comment: EASTERN COLORADO RIG ON WELL FOR SQUEEZE JOB.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location

Inspector Name: QUINT, CRAIG

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Ditches	Pass			

S/U/V: Satisfactory Corrective Date: _____

Comment: LOCATION IS GRASSED OVER.

CA: _____