

Field Inspection Document #667500175  
Caerus WASHCO LLC – Operator #86610  
State 31-22, API #121-10695  
Pit Facility ID #107521

Photo Documentation April 19, 2013



State 31-22 Tank Battery



Widespread accumulations of oily waste and uncontrolled erosion.





Separator and shed surrounded by oily waste.



Separator shed interior



Unused equipment stored on location. Widespread soil erosion.



Produced water tank, junk & trash. No berms. Widespread erosion.



East side water pit looking south. E&P waste from water pit improperly stored.



Windblown sand covering pasture adjacent south side of water pit approx 140' x 200'



Erosion - west berm water pit looking south



Surface impact adjacent west berm water pit (looking east) approx 200' x 200'



Oily waste north side water pit.



Wellhead – oily waste, leaks



Pumping unit – unprotected belt drive.



Dripping equipment at battery