

Inspector Name: LONGWORTH, MIKE

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

04/30/2013

Document Number:

663800931

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|---------------|---------------|------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>272758</u> | <u>334992</u> | <u>LONGWORTH, MIKE</u> | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------------|--------------|--------------------------------|---------|
| Insp., General | 970-285-2665 | cogcc.inspections@encana.com | |
| WESTERDALE, BARBARA | | barbara.westerdale@state.co.us | |
| AHLSTRAND, DENNIS | | dennis.ahlstrand@state.co.us | |

Compliance Summary:QtrQtr: NESW Sec: 2 Twp: 7S Range: 94W**Inspector Comment:**

045-10147 & 045-10148 have spud dates but no sight of them on location.

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------------------------------|
| 210912 | WELL | PR | 01/01/2005 | GW | 045-06670 | FEDERAL K-2-7-94-S | <input type="checkbox"/> |
| 272757 | WELL | XX | 06/25/2004 | LO | 045-10148 | SAVAGE FED 2-314D | <input checked="" type="checkbox"/> |
| 272758 | WELL | XX | 06/25/2004 | LO | 045-10147 | SAVAGE FED 2-324D | <input checked="" type="checkbox"/> |

Equipment:**Location Inventory**

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

LocationEmergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

Inspector Name: LONGWORTH, MIKE

☐ Multiple Spills and Releases?

| | | |
|-----------------|---------|--|
| Venting: | | |
| Yes/No | Comment | |
| | | |

| | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 334992

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

| | | | |
|--------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
| | | | |

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 272757 Type: WELL API Number: 045-10148 Status: XX Insp. Status: ND

Facility ID: 272758 Type: WELL API Number: 045-10147 Status: XX Insp. Status: ND

Environmental**Spills/Releases:**

Inspector Name: LONGWORTH, MIKE

| | | |
|--|------------------------------|-------------------------------|
| Type of Spill: _____ | Description: _____ | Estimated Spill Volume: _____ |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | | |
| Corrective Action: _____ | | Date: _____ |
| Reportable: _____ | GPS: Lat _____ | Long _____ |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____ | |

| | | | |
|------------------------|-------------------|-------------|------------|
| Water Well: | | Lat _____ | Long _____ |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | |

Field Parameters:

Sample Location: _____

| |
|---|
| Emission Control Burner (ECB): _____ |
| Comment: _____ |
| Pilot: _____ Wildlife Protection Devices (fired vessels): _____ |

Reclamation - Storm Water - Pit

| | |
|--|---|
| Interim Reclamation: | |
| Date Interim Reclamation Started: _____ | Date Interim Reclamation Completed: _____ |
| Land Use: _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| 1003a. | Debris removed? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Waste Material Onsite? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Unused or unneeded equipment onsite? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Pit, cellars, rat holes and other bores closed? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Guy line anchors removed? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Guy line anchors marked? _____ CM _____ |
| | CA _____ CA Date _____ |
| 1003b. | Area no longer in use? _____ Production areas stabilized ? _____ |
| 1003c. | Compacted areas have been cross ripped? _____ |
| 1003d. | Drilling pit closed? _____ Subsidence over on drill pit? _____ |
| | Cuttings management: _____ |
| 1003e. | Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ |
| | Production areas have been stabilized? _____ Segregated soils have been replaced? _____ |
| RESTORATION AND REVEGETATION | |
| <u>Cropland</u> | |

Inspector Name: LONGWORTH, MIKE

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| 045-10147 & 045-10148 have spud dates but no sight of them on location. | longworm | 04/30/2013 |