



Bison Oil Well Cementing Inc.
Suite 102
Denver, CO 80202
303-296-3010

Bill To	Noble Energy Inc. Attn: Accounting 1625 Broadway Ste 2000 Denver, CO 80202
---------	---

Date	6/25/2012
Invoice #	11088

Invoice

Location	Well Name & No.	Terms	Job Type
Weid, CO.	Rehder X06-32D	Net 30	Surface Pump
Item	Description	Qty	U/M

Pump surface	PUMP Charge-surface pipe	1	1,400.00	-15.00%	-210.00	540.00	-81.00	225.00	-33.75	1,840.25	4,872.75T	-730.91	1,825.00T	-273.75	37.50T	-5.63	5,724.96
Discount 15%																	
MILEAGE	Milage charge	360	1.50	-15.00%	-210.00	540.00	-81.00	225.00	-33.75	1,840.25	4,872.75T	-730.91	1,825.00T	-273.75	37.50T	-5.63	5,724.96
Discount 15%																	
Data Acquisition ...	Data Acquisition Charge	1	225.00	-15.00%	-33.75	1,840.25	4,872.75T	-730.91	1,825.00T	-273.75	37.50T	-5.63	5,724.96				
Discount 15%																	
BFN III Summer ...	BFN III Blend	267	18.25	-15.00%	-210.00	540.00	-81.00	225.00	-33.75	1,840.25	4,872.75T	-730.91	1,825.00T	-273.75	37.50T	-5.63	5,724.96
Discount 15%																	
Neat Type III	Neat Type III	100	18.25	-15.00%	-210.00	540.00	-81.00	225.00	-33.75	1,840.25	4,872.75T	-730.91	1,825.00T	-273.75	37.50T	-5.63	5,724.96
Discount 15%																	
KCL Mud Flush	(BHS 117)	5	7.50	-15.00%	-112.50	1,727.50	4,715.00T	-707.25	1,647.75T	4,007.75T							
Discount 15%																	
Subtotal of Materials																	

Please Remit Payment To:

Bison Oil Well Cementing, Inc.
P.O. Box 29671
Thornton, CO 80229

Subtotal	\$7,565.21
Sales Tax (2.9%)	\$166.02
Total	\$7,731.23
Balance Due	\$7,731.23

BISON OIL WELL CEMENTING, INC.



1738 Wynkoop St., Ste. 102
 Denver, Colorado 80202
 Phone: 303-296-3010
 Fax: 303-298-8143
 E-mail: bisonoil@gwestooffice.net

SERVICE INVOICE

№ 11088

WELL NO. AND FARM		CHARGE TO	
Kender 406-32-1		Noble	
COUNTY	WELL LOCATION	SEC.	TWP.
Weld	6	2	65
STATE	RANGE	DELIVERED TO	CONTRACTOR
CO	65	W&A 22137	3 Ensign well
DATE		LOCATION	CODE
6-25-12		Shop	
SHIPPED VIA		LOCATION	CODE
3102 - 2204		2 W&A 22137	
TYPE AND PURPOSE OF JOB		LOCATION	CODE
Surface		3 Shop	
WELL TYPE		CODE	
GHS			

PRICE REFERENCE	DESCRIPTION	QTY.	UNITS	MEAS.	UNIT PRICE	AMOUNT
	Pump Charge	1	EA		1400.00	1400.00
	Cement BFW III 390 B&A-1.25 105 B&A-1	100	SKS		1825.00	1825.00
	Cement B&A Net	267	SKS		1825.00	4872.75
	B&A-1	4	QTS		750.00	3000.00
	Day	8	QZ		1500.00	12000.00
	Milage 100 Per mile Round trip 60 mile min	3	EA		1800.00	5400.00
	Well Name & Number: Kender 406-32-1	1	EA		2250.00	2250.00
	AFE Number: 135849					
	TASK (DRL COMP. W/O. PSA)					
	EXP TYPE					
	ACTG CODE					
	DOLLAR TOTAL (B&A APPV)					
	FIELD APV Weight					
	TAX REFERENCES					
	ROUTE TO APPROVER					
	MAIL TO: NOBLE ENERGY INC.					
	ATTN: ACCOUNTS PAYABLE					
	TAXES WILL BE ADDED AT CORPORATE OFFICE					
	DENVER, CO 80202					
	NO INVOICE WILL BE PAID W/O ALL					
	ATTACHED SIGNED FIELD TICKETS					

If this account is not paid within 30 days of invoice date a FINANCE CHARGE will be made. Computed at a single monthly rate of 1 1/2% which is equal to an ANNUAL PERCENTAGE RATE OF 18%.

SUBJECT TO CORRECTION

1335.04	8892.45	166.02	7731.23
SUB TOTAL		2.9%	
TAX			
TOTAL			

mt Roy

Customer or His Agent

Bison Oil Well Cementing, Inc. Representative

Customers hereby acknowledge and specifically agree to the terms and conditions on this work order, including, without limitation, the provisions on the reverse side hereof which include the release and indemnity.

BISON OIL WELL CEMENTING, INC.



1738 Wynkoop St., Ste. 102
Denver, Colorado 80202
Phone: 303-296-3010
Fax: 303-298-8143
E-mail: bisonoil1@qwestoffice.net

TREATMENT REPORT

DATE	6-25-12	WELL NAME	Rehder 1006-32-D	SECTION	4	TWP	2	RGE	65	COUNTY	Weld	FORMATION
------	---------	-----------	------------------	---------	---	-----	---	-----	----	--------	------	-----------

CHARGE TO	Noble	OWNER	
MAILING ADDRESS	Noble		
CITY	Noble		
STATE ZIP CODE	6:45 AM		
TIME ARRIVED ON LOCATION	6:45 AM		
TIME LEFT LOCATION	10:43		
DISTANCE TO LOCATION			
CONTRACTOR	Ensign 221		
OPERATOR	Noble		

PERFORMATIONS	TUBING SIZE	12 1/4	TUBING DEPTH	1050	TUBING WEIGHT	997.12	CASING SIZE	8 5/8	CASING DEPTH	1040.38	CASING WEIGHT	24180	CASING CONDITION	Good
TREATMENT VIA														
TYPE OF TREATMENT														
TUBING														
STRING														
SURFACE PIPE ANNULUS LONG														
INSTRUCTED														

PRESSURE SUMMARY		PRESSURE LIMITATIONS	
BREAKDOWN or CIRCULATING	psi	INITIAL BPM	
FINAL DISPLACEMENT	psi	MINIMUM BPM	
ANNULUS	psi	MAXIMUM BPM	
5 MIN SIP	psi	AVERAGE BPM	
15 MIN SIP	psi		
MINIMUM	psi		
MAXIMUM	psi		
OTHER			

INSTRUCTIONS PRIOR TO JOB		TREATMENT RATE	
Rig up, Safety, PST TEST 500 PSI, 40 BBLs spacer, 40 BBLs cement, 10% excess per company man, 1.32 yield at 14.8 lbs then mix + pump tail of 100 sts (0% excess) 1.32 yield at 15.2, Release Plug Displace 43.5 BBLs the bump plug 150 PSI over 14.8, wait 10 min, Release PST Wash up		TREATMENT	
JOB SUMMARY		TREATMENT RATE	
Description of Job Events		TREATMENT	
Cement stop 9:11 AM Displace 9:39 AM		TREATMENT	
Safety meeting 8:00 AM		TREATMENT	
Cement start 8:45 AM		TREATMENT	

JOB SUMMARY		TREATMENT RATE	
Description of Job Events		TREATMENT	
Cement stop 9:11 AM Displace 9:39 AM		TREATMENT	
Safety meeting 8:00 AM		TREATMENT	
Cement start 8:45 AM		TREATMENT	

DATE	6-25-12	TITLE	
AUTHORIZATION TO PROCEED			

Customers hereby acknowledge and specifically agree to the terms and conditions on this work order, including, without limitation, the provisions on the reverse side hereof which include the release and indemnity.

Bison Oil Well Cementing, Inc
1738 Wynkoop St., Ste. 102
Denver, CO 80202
303-296-3010
www.bisonoilwell.com



Cementing Customer Satisfaction Survey

Service Date	6-25-12
Invoice Amount	
Well Name	Rehta
Well Location	WCE 32+37
County	Weld
SEC/WP/RNG	6-2-65
State	CO
Supervisor Name	M. Ke Rosalez
Employee Name	
Exposure Hours (Per Employee)	4
Invoice Number	11088
Well Permit Number	
Well Type	Gas
Well Number	KOL-32-D
Lease	
Job Type	Surface Pip
Company Name	MOBIL
Customer Representative	M. Ke
Customer Phone Number	

Did we encounter any problems on this job? Yes/No

To Be Completed By Customer

Rating/Description	
5 - Superior Performance (Established new quality / performance standards)	
4 - Exceeded Expectations (Provided more than what was required / expected)	
3 - Met Expectations (Did what was expected)	
2 - Below Expectations (Job problems / failures occurred [* Recovery made])	
1 - Poor Performance (Job problems / failures occurred [* Some recovery made])	
* Recovery: resolved issue(s) on jobsite in a timely and professional manner	

RATING / CATEGORY

Personnel -	
Equipment -	
Job Design -	
Product / Material -	
Health & Safety -	
Environmental -	
Timeliness -	
Condition / Appearance -	
Communication -	
Improvement -	

CUSTOMER SATISFACTION RATING

Did our personnel perform to your satisfaction?	
Did our equipment perform to your satisfaction?	
Did we perform the job to the agreed upon design?	
Did our products and materials perform as you expected?	
Did we perform in a safe and careful manner (Pre / post migs, PPE, TSMR, etc..) ?	
Did we perform in an environmentally sound manner (Spills, leaks, cleanup, etc..) ?	
Was job performed as scheduled (On time to site, accessible to customer, completed when expected)?	
Did the equipment condition and appearance meet your expectation?	
How well did our personnel communicate during mobilization, rig up, and job execution?	
What can we do to improve our service?	

Please Circle:

Yes / No	Did an accident or injury occur?
Yes / No	Did an injury requiring medical treatment occur?
Yes / No	Did a first-aid injury occur?
Yes / No	Did a vehicle accident occur?
Yes / No	Was a post-job safety meeting held?

Additional Comments:

Customer Representative's Signature


[Signature]

THE INFORMATION HEREIN IS CORRECT -

Any additional Customer Comments or HSE concerns should be described on the back of this form

Date

6-25-12



INVOICE 11088

Facility Name and Location	Rehder 906-32-1	Nearest Emergency Medical Service Number (Other than 911)	0262
Work to be Undertaken	Scuba & P		

☒ Hard Hat ☒ Safety Glasses w/sideshields ☒ Safety Toed Footwear ☐ Personal Methane Monitor ☐ Verify Safety Training

☐ Flame Resistant Clothing ☐ New on Job Review ☐ Onsite Orientation ☐ Other (specify) _____

☒ Job Safety Analysis Reviewed (if applicable)

☐ NORM or Other Radiation

☐ Hazardous Atmosphere

☐ Hazardous Substance

- ☒ Extreme Heat/Cold
- ☒ Sharp Impact
- ☐ Electrical Current
- ☒ Compressed Air
- ☒ Flammable/Combustible/Explosives
- ☒ Trapped Pressure
- ☒ Overhead work/suspended loads/crains/lifts
- ☐ Noise Levels
- ☐ Slips/Trips
- ☐ Vibration/Working Surfaces

☐ Overexertion/Heavy Lifting
☒ Pinch Points/Moving/Rotating Equipment
☐ Waste Handling/Disposal
☐ MSDS's Reviewed
☐ Insects/Sparks/etc.
☐ Sharp Tools

☒ Flying Particles
☒ Overhead Power Lines
☐ Excavation Collapse
☐ Walk Around Site Assessment

ADDITIONAL PPE REQUIREMENT (based on the job specific hazards, check all that apply)	
Eyes/Face	
Hands	
Feet	
Other	

☐ Tinted Lenses
☐ Goggles
☐ Field
☐ Chemical Resistant Gloves
☐ Heat Resistant Gloves
☐ Rubber Boots
☐ Over Boots
☐ Air Purifying Respirator
☐ Supplied Air Respirator

☐ Fall Protection
☐ Hearing Protection
☐ Respiratory Protection
☐ Cotton or Leather Gloves
☐ Dielectric Gloves
☐ Dielectric Boots
☐ Personal H2S Monitor (if in sour area)
☐ Chemical Resistant Clothing
☐ Fall Arrest & Snatch

EMERGENCY PREPARATIONS

Additional Topics Covered:

- ☒ Muster Areas
- ☒ Communication Methods
- ☒ Means of Egress
- ☒ Emergency Equipment

Attendees (Signature)/Company	Attendees (Signature)/Company
-------------------------------	-------------------------------

115388

<p>3. 11. 2014</p> <p>Handwritten notes</p>	<p>Handwritten notes</p>
---	--------------------------

<p> Mary Emma 220 EXISTON </p>	<p> Michael </p>
---	---

Other considerations and field notes: