

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

05/21/2013

Document Number:

670200480

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>275249</u>	<u>335079</u>	<u>BURGER, CRAIG</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 10071 Name of Operator: BARRETT CORPORATION* BILL

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron		aaxelson@billbarrettcorp.com	Production Foreman
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor
Merry, Jesse		jmerry@billbarrettcorp.com	Area Superintendent

Compliance Summary:

QtrQtr: <u>SWSE</u>		Sec: <u>25</u>	Twp: <u>6S</u>		Range: <u>92W</u>		
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/12/2011	200325911	PR	PR	S			N
10/27/2010	200283911	PR	PR	S			N
07/11/2006	200099146	PR	PR	S		P	N

Inspector Comment:

Spoke to pumper and he indicated ignitor will be relit and drum will be dealt with.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
54	WELL	PR	04/17/2008	GW	045-15433	SCOTT 34A-25-692	<input checked="" type="checkbox"/>
275249	WELL	PR	11/01/2012	GW	045-13498	SCOTT 24B-25-692	<input checked="" type="checkbox"/>
275250	WELL	PR	07/28/2005	GW	045-13499	SCOTT 34C-25-692	<input checked="" type="checkbox"/>
275864	WELL	PR	07/27/2005	GW	045-10393	SCOTT 24D-25-692	<input checked="" type="checkbox"/>
275866	WELL	PR	04/06/2008	GW	045-10391	SCOTT 24C-25-692	<input checked="" type="checkbox"/>
292244	WELL	PR	04/17/2008	GW	045-14653	SCOTT 34B-25-692	<input checked="" type="checkbox"/>
292245	WELL	PR	04/14/2008	GW	045-14652	SCOTT 34D-25-692	<input checked="" type="checkbox"/>
292246	WELL	PR	04/25/2008	GW	045-14651	SCOTT 33A-25-692	<input checked="" type="checkbox"/>
292247	WELL	PR	04/08/2008	GW	045-14650	SCOTT 24A-25-692	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory			
WELLHEAD	Satisfactory			
BATTERY	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
IGNITOR/COMBUST OR	Satisfactory	cattle panel		
SEPARATOR	Satisfactory	cattle panel		
TANK BATTERY	Satisfactory	cattle panel		
WELLHEAD	Satisfactory	cattle panel		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Emission Control Device	2	Unsatisfactory	Pilot off on one unit	Keep pilot light on.	05/31/2013
Plunger Lift	9	Satisfactory			
Gathering Line	1	Satisfactory			
Horizontal Heated Separator	9	Satisfactory	Earth berm containment.		
Bird Protectors	9	Satisfactory			
Deadman # & Marked	2	Satisfactory	some unmarked		
Ancillary equipment	1	Satisfactory	descaler unit		
Pig Station	1	Satisfactory			
Gas Meter Run	2	Satisfactory			

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	1	100 BBLS	STEEL AST	39.491600,-107.614780	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Inadequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment		HDPE lined earth berm			
Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	4	300 BBLS	HEATED STEEL AST	39.491460,-107.614940	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
<u>Paint</u>					
Condition	Inadequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
YES	bradenheads open				
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	
Ignitor/Combustor	Unsatisfactory	Pilot off on one unit.	Keep pilot light on.	05/31/2013	

Predrill

Location ID: 335079

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 54 Type: WELL API Number: 045-15433 Status: PR Insp. Status: PR

Producing Well

Comment: plunger lift

Facility ID: 275249 Type: WELL API Number: 045-13498 Status: PR Insp. Status: PR

Producing WellComment: Facility ID: 275250 Type: WELL API Number: 045-13499 Status: PR Insp. Status: PR**Producing Well**Comment: Facility ID: 275864 Type: WELL API Number: 045-10393 Status: PR Insp. Status: PR**Producing Well**Comment: Facility ID: 275866 Type: WELL API Number: 045-10391 Status: PR Insp. Status: PR**Producing Well**Comment: Facility ID: 292244 Type: WELL API Number: 045-14653 Status: PR Insp. Status: PR**Producing Well**Comment: Facility ID: 292245 Type: WELL API Number: 045-14652 Status: PR Insp. Status: PR**Producing Well**Comment: Facility ID: 292246 Type: WELL API Number: 045-14651 Status: PR Insp. Status: PR**Producing Well**Comment: Facility ID: 292247 Type: WELL API Number: 045-14650 Status: PR Insp. Status: PR**Producing Well**Comment: **Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:Sample Location:

Inspector Name: BURGER, CRAIG

Emission Control Burner (ECB): Y

Comment: Pilot off on one of two units.

Pilot: OFF Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM CA CA Date
Waste Material Onsite? Pass CM CA CA Date
Unused or unneeded equipment onsite? Pass CM CA CA Date
Pit, cellars, rat holes and other bores closed? Pass CM CA CA Date
Guy line anchors removed? CM CA CA Date
Guy line anchors marked? In CM CA CA Date

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized? Pass Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003 f. Weeds Noxious weeds? P

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Inspector Name: BURGER, CRAIG

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
Debris removed _____ No disturbance /Location never built _____
Access Roads Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____
Comment: _____
Corrective Action: _____ Date _____

Overall Final Reclamation

Multi-Well Location



Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Sediment Traps	Pass	Gravel	Pass			
Rip Rap	Pass	Check Dams				
Ditches	Pass	Culverts	Pass			
Sodding	Pass	Ditches		MHSP	Fail	

S/U/V: **Unsatisfactory** Corrective Date: **06/07/2013**

Comment: An unlabeled drum that contains fluid is on the ground adjacent to wellhead 045-13499. Erosion control measures in access road ditch are being overloaded by flow from flood irrigation of ranchers field.

CA: Remove drum.